

ASS. REC. BY:

REF:

TP/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 4806

Yr Regn:

07 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c.

1995

Colour

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

332217

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VI-1 ABL 15 AUC 283456

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt /

Brake: Inorder / Jammed / Leaked / Burnt /

Mod: Nil / S/Rlm / STD A/Rlm /

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / JIR / SUMI /

TOYO / YOKO or

Daiwa

Front

Rear

R/Bal.

6

mm

R/Bal.

7

mm

L/Bal.

6

mm

L/Bal.

7

mm

D.O.A.

18/8/20

D.O.A.

19/8/2020

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S R & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Not Authoised
1/1/2017

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 480G

AAD2008-076

Vehicle No.: 19 AUG 2020
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

SHD 480G

VF1ABL15AUC283456

RENAULT

LATITUDE

18.8.2020

Direct Asia

3/7/2017

PART		LIST	
1	BUMPER COVER FRT	\$ CM	747.20 ✓
1	BUMPER SPOILER FRT	\$ DIT	344.70 ✓
1	BUMPER ABSORBER FRT	\$ R	394.68 ✓
1	BUMPER BRACKET FRT LH (Headlamp Lower)	\$ CM	116.47 ✓
1	BUMPER RETAINER FRT LH	\$ CM	101.40 ✓
1	BUMPER SUPPORT FRT	\$ R	10.70 X
1	BUMPER UNDERTRAY FRT	\$ R	292.50
1	BUMPER GRILLE LOWER FRT	\$ R	147.00
1	BUMPER FOG LAMP GRILLE LH	\$ R	207.21
1	BUMPER BEAM FRT	\$ R	663.70
1	RADIATOR GRILLE	\$ R	969.90 X
1	RADIATOR GRILLE BADGE 'RENAULT'	\$ R	225.36
1	RADIATOR GRILLE FRAME	\$ R	686.00
1	FRAME FULL SUPPORT PANEL	\$ R	592.70
1	FRAME FULL SUPPORT BRACKET	\$ R	41.60
1	FRONT BRACE PANEL	\$ R	177.22
1	HEADLAMP LH	\$ MY CM	743.60 ✓
1	HEADLAMP PANEL FRT LH	\$ R	128.30 X
1	BONNET	\$ R	1,312.70 X
1	BONNET STRUT LH	\$ R	53.30 X
1	BONNET HINGE LH	\$ R	236.50 X
1	BONNET CABLE	\$ R	55.20 X
1	BONNET CABLE COVER	\$ R	80.60 X
1	BONNET LOCK	\$ R	152.80 X
1	FENDER PANEL FRT LH	\$ R	437.10 ✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 480G**AAD2008-076**

1	WHEELARCH FRT LH	\$	CM	191.40	✓
1	FENDER BRACKET LOWER LH	\$	K	11.80	} X
1	FENDER INSULATOR LH	\$	SL	66.30	
1	FENDER BRACKET FRT LH	\$	K	106.40	
1	FENDER PANEL INNER FRT LH	\$	K	858.30	
1	FENDER PANEL REINFORCEMENT FRT LH	\$	K	642.40	
1	CHASSIS PANEL FRT LH	\$	K	655.80	
1	CHASSIS PANEL SUPPORT FRT LH	\$	SL	431.70	} X
1	WHEEL HOUSING PANEL FRT LH	\$	K	2,698.60	
1	AIR CLEANER LOWER	\$	R	271.26	✓
1	AIR CLEANER HOSE	\$	SL	175.85	X
1	BASE BATTERY TRAY	\$	SL	363.40	X
1	AIR CLEANER BOX	\$	SL	464.20	X
1	SUBFRAME OUTER FRT	\$	R	1,094.20	✓
1	SUBFRAME BRACKET OUTER LH	\$	SL	49.00	X
1	SUBFRAME INNER FRT	\$	SL	2,284.80	X
1	SUBFRAME SUPPORT INNER	\$	SL	69.50	X
1	SUBFRAME BRACKET INNER LH	\$	SL	101.00	X
1	AUTO COMPUTER	\$	SL	1,287.30	X
1	INJECTION COMPUTER	\$	SL	2,706.30	X
1	STEERING PINION RACK	\$	R/H	3,765.30	✓
1	STEERING PUMP ELECTRIC	\$	SL	2,026.70	X
1	ENGINE HARNESS	\$	SL	1,501.60	X
1	ENGINE UNDERTRAY	\$	SL	583.10	X
1	BATTERY	\$	SL	350.00	X
1	BATTERY COVER	\$	SL	363.40	X
1	LOWER ARM LH L70Y	\$	D/Y	192.70	✓
1	KNUCKLE ARM LH L70Y	\$	R	481.50	✓
1	ABSORBER FRT LH L70Y	\$	R	274.10	✓
1	ABSORBER MOUNTING KIT LH	\$	R	212.30	✓
1	ABSORBER DUST COVER	\$	SL	76.30	X
1	DRIVESHAFT LH	\$	K	1,355.70	X
1	KNUCKLE HUB+BEARING LH	\$	R	272.30	✓
1	STABILIZER BAR FRT	\$	SL	427.90	X

Trans-cab Auto Services Pte Ltd

AAD2008-076

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 480G

1	STABILIZER LINK FRT	\$	Sm	69.50	}	X	
1	ABS SENSOR FRT LH	\$	Sm	152.50			
1	DOOR PANEL FRT LH	\$	N	2,844.66			
1	DOOR HINGE UPPER FRT LH	\$	N	274.50			
1	DOOR HINGE LOWER FRT LH	\$	N	300.55			
1	DOOR CHECK FRT LH	\$	Sm	90.90			
1	DOOR FINISHER FRT LH	\$	Sm	258.90			
1	DOOR FINISHER CLIP KIT FRT LH	\$	nn	94.00			
1	DOOR SEAL FRT LH	\$	nn	69.60			
1	DOOR MIRROR ASSY LH	\$	Sm	1,483.40			
1	DOOR WAIST SEAL OUTER FRT LH	\$	Sm	92.20			
1	ROCKER PANEL OUTER LH	\$	N	1,184.99			
1	TOW COVER FRT	\$	Sm	60.90			
TOTAL		\$		42,307.44			
10%		\$		4,230.74			
		\$		38,076.70			

Special Nett

Special Nett				
1SET	RADIATOR GRILLE FRAME CLIP	\$	nn	60.00 X
1SET	BUMPER CLIP FRT	\$	nn	80.00
1	BUMPER BRACKET CLIP FRT	\$	nn	65.00
1	BUMPER SUPPORT CLIP FRT	\$	nn	10.00
1SET	BUMPER RETAINER CLIP FRT	\$	nn	70.00
1SET	RADIATOR GRILLE SCREW	\$	nn	55.00
1SET	BUMPER GRILLE LOWER CLIP	\$	nn	70.00
1	BUMPER FOG LAMP GRILLE CLIP	\$	nn	55.00
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00
2	FRAME FULL SUPPORT PANEL NUT	\$	nn	40.00
2	FRAME FULL SUPPORT PANEL STUD	\$	nn	50.00
1	Windscreen moulding	\$	nn	200.00
2	FRONT WINDSCREEN SEALANT	\$	nn	150.00
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	nn	130.00
1SET	Front licence plate with holder	\$	Sh	120.00
1SET	WHEELARCH CLIP FRT	\$	nn	60.00

Trans-cab Auto Services Pte Ltd

AAD2008-076

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 480G

1	ROCKER PANEL CLIP	\$	nn	60.00	X
1	FRONT DOOR STICKER "Trans-Cab"	\$	nn	80.00	X
1	Front Renault Tyre 215/60/16	\$	pu	330.00	509m
1	Front Renault tyre rim	\$	B	380.00	
1	FRONT DOOR STICKER 'Classic'	\$	nn	80.00	} X
3 Can	Power Steering Fluid	\$	nn	80.00	
1SET	FENDER INSULATOR CLIP	\$	nn	50.00	
1	BONNET CABLE CLIP	\$	nn	30.00	
2	SEAM SEALANT (FOR BODY REPAIR)	\$	nn	200.00	
TOTAL		\$		2,575.00	
TOTAL PARTS		\$		40,651.70	

LABOUR

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.

\$ nn 380.00 X

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,200.00 4001

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

To rust-proofing and apply undercoat of the affected areas.

\$ 250.00 301

To check steering geometry and computer wheel alignment

\$ 220.00 601

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ nn 380.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 480G**AAD2008-076**

To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	nn	440.00	X
To transfer of tire, rim and on wheel balancing.	\$		170.00	20/
To dismantle and refit engine cross-member and engine mounting.	\$	nn	380.00	X
To remove and refit battery, electrical wiring, fuse box and relay to enable repair.	\$	nn	450.00	X
Putty and spray painting of the affected portion.	\$		2,200.00	660/
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn	170.00	X
To transfer of front windscreen glass to facilitate bodywork repair.	\$	4	170.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	4	170.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	4	170.00	X
To check ABS and brake efficiency, final checking and testing.	\$	4	380.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	4	170.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$		380.00	200/

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 480G

AAD2008-076

Towing Fees

\$

170.00

501

To Check Electrical Lighting Concerned.

\$

170.00

201

To conduct and perform a comprehensive vehicle
diagnostic check and reset vehicle warning
indicators.

\$

450.00

X

TOTAL

\$

9,850.00

Over All Total

\$

50,501.70

Repair Days (LUMP SUM)

25 DAYS

4 days

For Official Use

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/08/2020 15:22
Date Of Accident	18/08/2020 02:55
Exact Location Of Accident	UPPER CHANGI ROAD EAST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD480G
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	2XXXXX878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P2348706
Cover Note Number	

Driver

Name of Driver	TOH KOK SHONG
NRIC No	SXXXX457A
Date Of Birth	20/08/1978
Occupation	OUTDOOR
Date Of Driving Pass	24/07/1998
Driving Experience	22 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97550405
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 672B YISHUN AVENUE 4
#12-548
Postcode 762672
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 3
Passenger 1 NAME: : UNKNOWN
GENDER: : MALE
Passenger 2 NAME: : UNKNOWN
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name ANG MO KIO NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address ROAD: 51 ANG MO KIO AVE 9 , POSTCODE: 569784 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-4849999 - FAX NO: 62181399
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : T/20200818/2058

Attachment(s)


Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: FILE TOO BIG
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMC946B
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

GIARMC SketchPlanForm_V3

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

2