



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2202607

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 09/05/2022
Reference CC4/FCI20008701/Kea3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. GBA 8991H
Insured Veh. SH 8269Y
Claim No. D20003256MFSH
Policy No. D-20094922MFSH
Accident Date 14/08/2020
Inspection Date 19/08/2020

Description	Total
Survey Inspection	380.00
Digital Photographs	
Transportation	
Subtotal	380.00
GST (7%)	26.60
Grand Total	406.60

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM

Your Ref : D20003256MFSH

Date: 09th May 2022

Our Ref : CC4/FCI20008701/Kea3q2

M/s FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
Singapore 068877
(The Motor Claims Department)

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE GBA 8991H
INSURED VEHICLE: SH 8269Y
ACCIDENT ON 14/08/2020

Instruction was received to inspect the vehicle Reg. No. GBA 8991H. The inspection was conducted on 19/08/2020 at the premises of M/s Chew Goon Motor, Blk 10 Ang Mo Kio Ind Park 2A #01-15/16/17, Ave 5, AMK Autopoint, Singapore 568047.

The following vehicle information was recorded:

Registration Number	: GBA 8991H
Make/Model	: OPEL COMBO-C 1.3DTJ MTA E4
Year of Registration	: 2008
Body Colour	: Blue
Chassis Number	: W0L0XCF2584047948
Engine Capacity	: 1248 cc

The vehicle sustained damages at the o/s body. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 16,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 10,347.00
Nett Liability	<u>S\$ 5,653.00</u> =====

Vehicle Inspected By:



KONG SENG CHEONG
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBA 8991H

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

