

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Authorized
61 Sup @ 2, 7/10/19
Primary After Painting
12 days

To: First Capital Insurance Limited

Policy No: _____ Third Party

Date: _____ 18.08.2020

Accident Date : 14.08.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Opel Combo" Reg. No. GBA8991H Claiming Against Your Insured Veh. No. SH8269Y		
1pc	Front Bumper		
10pcs	Front Bumper Clips		
1pc	Front Bumper Corner Retainer RH		
1pc	Headlamp RH		
1pc	Front Fender RH		
1pc	Front Fender Protector		
1pc	Front Fender Protector Clips		
8pcs	Front Fender Signal Lamp		
1pc	Front Fender Shield		
1pc	Front Fender Shield Clips		
8pcs	Front Door RH		
1pc	Front Door Top Hinge		
1pc	Front Door Lower Hinge		
1pc	Front Door Arrestor		
1pc	Front Door Protector		
1pc	Front Door Outer Handle		
1pc	Front Door Glass		
1pc	Front Door Glass Outer Moulding		
1pc	Front Door Glass Regulator		
1pc	Front Door Glass Regulator Motor		
1pc	Front Door Glass Guide		
1pc	Front Door Glass Channel		
1pc	Front Door Wiring Harness		
1pc	Front Door Inner Lock		
1pc	Front Door Weatherstrip		
1pc	Front Door Trim Board		
1pc	Front Door Trim Board Clips		
1pc	Front Door Frame Weatherstrip		
1pc	Front Door Speaker		
1pc	Rocker Panel RH		
1pc	Rocker Panel Inner Panel		
1pc	Driver's Seat Assy		
1pc	Speedometer Outer Casing		
1pc	Door 'B' Pillar RH		
1pc	Sliding Door RH		
1pc	Sliding Door Protector		
1pc	Rear Fender Protector RH		
1pc	Rear Fender Protector Clips		

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

C/F

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: First Capital Insurance Limited

Third Party
Policy No: _____

Date: 18.08.2020

Accident Date : 14.08.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Opel Combo" Reg. No. GBA8991H Claiming Against Your Insured Veh. No. SH8269Y		
		B/F	-
1pc	Rear Bumper		
1pc	Rear Bumper Clips		
1pc	Rear Wheel Rim		
1pc	Rear Wheel Bearing		
1pc	Rear Wheel Shock Absorber		
	Less 10%		-
	Front Door Side Protector		35.00 SN
	Front Door Glass Solar Film		180.00 SN
	Front Door Carbon Sticker		120.00 SN
	Rocker Panel Chip Resistant Primer		100.00 SN
	Sliding Door Company Register Lable		45.00 SN
	Sliding Door Carbon Sticker		120.00 SN
	Sliding Door Glass Sealant		50.00 SN
	Sliding Door Glass Fasterner		50.00 SN
	To Conduct Rear Electrical Check, Focus Headlamp		30.00
	To Dismantle / Transfer Door Fittings / Ancillary Accessories		150.00
	To Dismantle / Refit Sliding Door Glass		120.00
	To Dismantle / Refit Sliding Door Fittings / Ancillary Accessories		150.00
	To Dismantle / Refit Driver's Seat, Interior Floor Carpets etc		
	To Dismantle / Replace Front Under Carriage to Facilitate Repair		120.00
	To Conduct Computerize Wheel Alignment Test		80.00
	To Provide Transportation (Towing)		80.00
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		180.00
		B/F	1,610.00

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: First Capital Insurance Limited

Accident Date : 14.08.2020

Policy No: Third Party

Date: 18.08.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Opel Combo" Reg. No. GBA8991H Claiming Against Your Insured Veh. No. SH8269Y		
		C/F	1,610.00
	Labour Charge - Panel Beating, Repairing Headlamp Panel, Front Fender inner Panel, Floor Panel, Front Door Pillar, Rear O/S Fender, cnt, Weld Rocker Panel and Parts Replacement		1,600.00
	To Respray Affected Areas		1,400.00
		Total :	<u>4,610.00</u>