

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 46042

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0585/2020/NS
Date	:	19-Aug-20

Vehicle IN workshop. Please arrange for survey.

Your insured veh no : SJX 5571 R

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Chua Loh Kiat
Address	:	12A Nim green Singapore 807632
Telephone	:	(Office) +65 96192620
Type of Claim	:	Third Party Claims
Policy No.	:	DMPPHQ19-007555
Vehicle No	:	SKQ 7859 Z
Model Code	:	Audi A4 1.8T FSI MU 8K203
Model / Year	:	26/12/2014
Engine No	:	CJE 090093
Chassis No	:	WAUZZZ8K8FA046294
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	18-Aug-20
Place of Accident	:	Jalan Eunos Filter Lane Towards PIE Changi

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKQ 7859 Z

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00	✓
2	To dismantle and renew rear bumper and rear bumper spoiler. To inspect rear end panelling. Re-organise crash management components. Reinstall all parts removed.	\$ 1,050.00	500
3	To respray rear bumper.	\$ 900.00	550
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 2,422.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SKQ 7859 Z

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER <i>Rebent</i>	\$ 2,273.00 ✓	\$1,818.40
2	REAR BUMPER FIXING PARTS <i>new</i>	\$ 225.00 X	
3	REAR BUMPER SPOILER <i>new</i> ✓ Cut	\$ 264.00 ✓	\$ 210.80
4	REAR BUMPER CARRIER <i>X NN</i>	\$ 636.00 X	
5	REAR BUMPER BRACKET HOLDER - LH / RH <i>new</i> 2	\$ 440.00 +	
6	REAR BUMPER SECURING STRIP <i>new</i>	\$ 14.00 ✓	\$10.56
7	REAR BUMPER GUIDE SECTION - LH UPPER <i>new</i>	\$ 23.00 X	
8	REAR BUMPER GUIDE SECTION - RH UPPER <i>new</i>	\$ 22.00 +	
9	REAR PARKING AID SENSOR ✓ Damaged	TBC ✓	\$200.00
10	SUNDRIES <i>X NN</i>	\$ 200.00 X	
TOTAL SPARE PARTS CHARGES		: \$ 4,097.00	
TOTAL LABOUR CHARGES		: \$ 2,422.00	
GRAND TOTAL		: \$ 6,519.00	

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian
Surveyed Date : 21/08/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant