

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

(Email Address : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate

TP CLAIM

To : AIG Asia Pacific Insurance Pte Ltd
Motor Claims Dept

Date : 08 Sep 20

Dear Sirs :

Fax : 64193727

RE : ESTIMATE COST FOR TOYOTA ALTIS 1.6A - SLP6871L
ACCIDENT INVOLVING SLP6871L & SJM1907R ON 17/08/2020

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>	
1	Rear bumper	1pc	\$ 484.90	de✓
2	Rear bumper retainer @\$88.50ea	2pcs	\$ 177.00	Xnn
3	Rear bumper sponge	1pc	\$ 155.30	de✓
			\$ 817.20	640.20
	Less 25%		\$ (204.30)	480.15
			\$ 612.90	
4	Rear bumper sensor	1set	\$ 220.00	200nw✓
	<u>Labour Charge & Misc</u>			
	To remove, repair, replace & install damaged parts.	}	\$ 350.00	200
	To R & R sensor wiring.		\$ 80.00	30
	To putty & spray painting.		\$ 400.00	200
	Total		\$ 1,662.90	430

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

Tan Jm 97495749
WP 8/9/20

L/S. Resurvey after repair
tanjm@lkkauto.com

1110.15
L/S \$ 900
2 days