



# MBM WHEELPOWER PTE LTD



Your Ref: FBQ3054L  
Our Ref: EV58J

*Not Authorised*  
*U1 Lump @*  
*Pushing After Paint*  
*7 days*

To: MSIG  
CC  
Fax

Date: 19/8/2020  
From: Danny  
Fax: 64525333  
Contact: 93288668  
Make / Model: NISSAN NOTE 1.2X  
Chassis No.: JN1TBAE12Z0982103  
Engine No.: HR12117412B  
Year of Make: 2015  
Accident Date: 15 August 2020

ESTIMATE FOR VEHICLE NO. : EV58J

DESCRIPTION	QTY	List Price	
LH SIDE MIRROR	1	\$ 684.00	✓
LH SIDE MIRROR COVER	1	\$ 176.00	X
LH SIDE MIRROR SIGNAL LAMP	1	\$ 199.00	✓
LH SIDE MIRROR MOTOR	1	\$ 293.00	✓
FRONT BUMPER	1	\$ 939.00	X
FRONT LH FENDER	1	\$ 604.00	X
FRONT LH FENDER INNER SHIELD	1	\$ 140.00	✓
FRONT LH FENDER INNER SHIELD CLIPS	10	\$ 60.00	✓
FRONT LH DOOR	1	\$ 966.00	✓
REAR LH DOOR	1	\$ 966.00	X
LH SIDE SKIRT <i>rodke paint</i>	1	\$ 485.00	✓
BUMPER CLIPS	10	\$ 60.00	X
Total:		\$ 5,572.00	
LESS 10%:		\$ (1,114.40)	
Parts Total:		\$ 4,457.60	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

## LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	\$	1,200.00	7501
TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	\$	100.00	601
TO DISMANTLE & TRANSFER DOOR FITTINGS & MECHANISM TO NEW DOOR / FACILITATE REPAIR	\$	240.00	601
TO APPLY ANTI RUST COATING	\$	150.00	301
TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS	\$	100.00	601
TO REMOVE & REPLACE BUMPER SENSORS	\$	60.00	X
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	80.00	201
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	1,500.00	11001
Total:		\$ 7,887.60	
7% GST:		\$ 552.13	
Grand Total:		\$ 8,439.73	

Mbm wheelpower pte ltd

160 SIN MING DRIVE

#06-02

SIN MING AUTOCITY

t 62628888 f 64525333

Company Registration Number : 200204110W

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/08/2020 13:30
Date Of Accident	15/08/2020 18:30
Exact Location Of Accident	ALONG 33 LENG KEE ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	EV58J
Insured/Policyholder	
Name Of Registered Owner	ONG RONG QUAN
NRIC No	S8123016A
Email Address	RONGQUAN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92732962
Alternative Phone No	OFFICE-92732962

### Vehicle Particulars

Manufacturer	NISSAN
Model	NOTE
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5103592324-01
Cover Note Number	DRIVO CLASSIC, EW

### Driver

Name of Driver	QUAH YEW HUI PEARLY
NRIC No	S8433832Z
Date Of Birth	07/11/1984
Occupation	INDOOR
Date Of Driving Pass	17/04/2004
Driving Experience	16 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-94248236
Fax Number	
Contact Number	
Email Address	PEARLYZZ@GMAIL.COM

Address BLK 131B LORONG 1 TOA PAYOH #04-538  
 SINGAPORE  
 Postcode 312131  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured SPOUSE  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -

**General Information of the Accident**

Type Of Accident SIDE SWIPE  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 4  
 Passenger 1 NAME: : ONG RONG QUAN (HUSBAND)  
 GENDER: : MALE  
 Passenger 2 NAME: : NATASHA ONG (DAUGHTER)  
 GENDER: : FEMALE  
 Passenger 3 NAME: : JAKE (SON)  
 GENDER: : MALE

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?


**Circumstances of Accident**

I was travelling along Leng Kee Road (a single lane road), with the intention to turn left into the Toyota showroom ( 33 Leng Kee road). I had started signalling left about 150metres before the showroom entrance and was travelling slowly to prepare to turn left. There were vehicles parked along the left (parallel parking), including an oversized vehicle at the last parking slot just before the showroom entrance. I had observed a dark vehicle travelling behind me and no other vehicles to the left of my car. As I passed the oversized vehicle, I initiated my left turn into the entrance of the showroom. Shortly after, vehicle B travelling at a fast speed, squeezed between the oversized vehicle and my vehicle A, with the intention to overtake my car and to go straight. The motorcyclist admitted that he saw my left signal and overtook the dark coloured vehicle behind me on the left (movement from B1 to B2), and intended to overtake me on the left as well. He could not stop in time to avoid hitting my car. He impacted my left rear of the car and scraped along the left side of my car (B3). I stopped immediately to render assistance. I would like to add that the fact that vehicle B overtook the dark coloured vehicle which was behind me on the left and tried to overtake my vehicle A on the left, is clearly against the LTA traffic rules. I have an eye witness who was standing right in front of the accident and witnessed the entire sequence of the events. His name is Dasmond Gan Chao Wei (H/p: 9109 4866).

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: OID WILL RETRIEVE

ETCH PLAN



**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

I was travelling along Leng Kee Road (a single lane road), with the intention to turn left into the Toyota showroom ( 33 Leng Kee road). I had started signalling left about 150metres before the showroom entrance and was travelling slowly to prepare to turn left. There were vehicles parked along the left (parallel parking), including an oversized vehicle at the last parking slot just before the showroom entrance. I had observed a dark vehicle travelling behind me and no other vehicles to the left of my car. As I passed the oversized vehicle, I initiated my left turn into the entrance of the showroom. Shortly after, vehicle B travelling at a fast speed, squeezed between the oversized vehicle and my vehicle A, with the intention to overtake my car and to go straight. The motorcyclist admitted that he saw my left signal and overtook the dark coloured vehicle behind me on the left (movement from B1 to B2), and intended to overtake me on the left as well. He could not stop in time to avoid hitting my car. He impacted my left rear of the car and scraped along the left side of my car (B3). I stopped immediately to render assistance. I would like to add that the fact that vehicle B overtook the dark coloured vehicle which was behind me on the left and tried to overtake my vehicle A on the left, is clearly against the LTA traffic rules.

I have an eye witness who was standing right in front of the accident and witnessed the entire sequence of the events. His name is Dasmond Gan Chao Wei (H/p: 9109 4866).