



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2106730
INV Date 28/09/2021
Reference CC4/LPC20008710/Qga3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SG 5812D
Insured Veh. XE 9997D
Claim No. 19/20/20/VC00/023554
Policy No. Z/19/VC00/105396
Accident Date 14/08/2020
Inspection Date 19/08/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CC4/LPC20008710/Qga3q2

Date: 28/09/2021

Code: LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 9997D	Veh. Inspected	SG 5812D
Policy No.	Z/19/VC00/105396	Coverage (\$)	0.00
Claim No.	19/20/20/VC00/023554	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	19/08/2020

2. Vehicle Particulars & Condition

Make & Model	MAN A95	c.c	10518
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WMAA95ZZ7G7003460	Colour	MULTI COLOUR
Odometer	162294 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	CONTINENTAL	6 mm
L/H Front Tyre	275/70 R22.5	CONTINENTAL	6 mm
R/H Rear Tyre	275/70 R22.5	CONTINENTAL	6 mm
L/H Rear Tyre	275/70 R22.5	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/08/2020	Inspection Date	19/08/2020
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 5812D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	O/S FRP FRONT HEADLAMP COVER	CRUMPLED	975.00	975.00
1	FRP FRONT DOME	TO REPAIR SEE LABOUR	2,450.00	-
1	BATTERY PANEL	TO REPAIR SEE LABOUR	765.70	-
	LESS 10% DISCOUNT		-	-97.50
			4,190.70	877.50
SPECIAL NETT ITEMS				
1	ALUMINIUM SHEET (SN)	CRUMPLED	480.00	480.00
1	STICKER SMRT (SN)	NECESSARY	75.00	75.00
1	ADHESIVE DIRECT GLAZING (SN)	NECESSARY	37.00	37.00
1	PRIMER (SIKA 206 G+P) (SN)	NECESSARY	80.00	80.00
			672.00	672.00
LABOUR				
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF FRP FRONT DOME AND BATTERY PANEL .		2,650.00	2,120.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		1,296.00	956.00
			3,946.00	3,076.00
GRAND TOTAL			8,808.70	4,625.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,300.00

Report Ref No. CC4/LPC20008710/Qga3q2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SG 5812D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SG 5812D

RE-INSPECTION

