

Bifrost Auto Pte Ltd

Tel: +65 6452 4457 | Fax: +65 6452 4584

Co. Reg. No.: 201929175W

SMJ4186 P

Merc A250 Sport (BI)

WDD1760442J293261

2014

Total for spare parts	\$	-	2220.44
------------------------------	-----------	----------	----------------

Total for SP	\$	4,129.00
Sub-Total for Parts :	\$	4,129.00

S/No	Qty	Items	Unit Price	Amount	
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-	\$	800.00	200
2		To putty and spray paint on all accident damage parts and other accident	\$	600.00	250
3		To check wiring system to facilitate repair and refit the same	\$	150.00	30
4		Apply rust proofing on the adjacent panels	\$	60.00	X NN
5		Reset engine management system with diagnostic fault	\$	80.00	X NN
6		To supply under coating / putty on parts replaced	\$	80.00	X NN
7		To conduct headlight focus	\$	150.00	X NN
8		To remove & refit rear sensor	\$	60.00	40
9		To programming radar	\$	1,500.00	X NN
TOTAL AMOUNT :			\$	3,480.00	
OVERALL COST:			\$	7,609.00	

3 Days.

3600.44

-20%: 2850

Upsun Repair.

After repair photos.

Guo Qinf.

19/8/2020.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: