

(08/11/13) wef

ASS. REC. BY: *MG/145*

REF:

CS/CT120008717/USF3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

31/08/2020

1) TYPIST

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Photos

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

) S + RS, SI

)

)

)

Report Format :

Lump Sum

I.B.I: (\$ 2,000.00 L/S)

27/8/20 2/5 @ 2000 confirmed with Chris
(\$ 3,985.35/RED - 67%)

20/3/2020 20/3/2020 11/6/20

SUPER-ZEE MOTOR SERVICE

BLK 14 DEFU LANE 10 #01-402 SINGAPORE 539195 TEL: 6383 1913 FAX: 6383 9565
EMAIL: superzeemotor@gmail.com

19 Aug 2020

China Taiping Insurance (S) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Att: Motor Claims Dept

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authorized
24/8/20
2/c 2000
3 days
Tel: 9441. After
ny-

THIRD PARTY CLAIM

OWNER NAME : YONG SOW YIN
VEHICLE REG NO : SKP 3363 T
DATE OF ACCIDENT : 18 AUG 2020
PLACE OF ACCIDENT : CTE TOWARDS PIE
INVOLVING VEH NO : GBJ 6237 T

We append herewith our estimate for the repairs of Vehicle No SKP3363T as follows:

Materials Required

1 pc	Rear Bumper	De/cna	S\$1,305.80	✓
1 pc	Rear Bumper Lower Carrier	NS	S\$ 79.90	X
1 pc	Rear Bumper Reinforcement	su	S\$ 515.20	X
2 pcs	Rear Bumper Retainers	ny	S\$ 122.40	X
10 pcs	Rear Bumper Clips	rec	S\$ 65.00	✓
1 pc	Rear Bootlid	n	S\$1,234.80	X
1 pc	Rear Bootlid Emblem - Logo	ny	S\$ 79.40	X
	320i	rec	S\$ 78.70	✓
1 pc	Rear End Panel	n	S\$ 596.60	X
1 pc	Rear End Panel Top Garnish	ny	S\$ 95.30	X
10 pcs	Rear End Panel Top Garnish Clips	ny	S\$ 65.00	X
1 pc	Rear Exhaust Chrome Tailpipe	ny	S\$ 148.60	X
2 pcs	Parking Sensors	shoked	S\$ 474.80	✓

Less: 10% Discount

S\$4,861.50

S\$ 486.15

S\$4,375.35

Labour Charges

To dismantle & replace damaged parts and panelbeating	S\$ 650.00	300
To putty, apply primer & spraypaint affected portion	S\$ 750.00	450
To apply rustproofing on repaired, replaced panel	S\$ 150.00	X
To check electrical wiring functions	S\$ 60.00	30

S\$5,985.35

SUPER-ZEE MOTOR SERVICE

P-192430
102
1731.87
2511.87
202
2029