

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
 Toll-Free Number (1800-2255269)



303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

20 AUG 2020

E S T I M A T E

Estimate No. : b1 55803	Page No. : 1 of 4
Date Estimated : 20/08/2020	
Prepared By : Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR - Hon Thiam Heng Jason 75A Redhill Road #22-58 Singapore 151075	- ACCOUNT - 219 India Int'L Insurance Pte Ltd 64 Cecil Street #04-05 IOB Building Singapore 049711
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDZ2211K	WBA5R120X0AK73114	24/06/2019	330i LIM	0

DESCRIPTION	VALUE		
To replace left dide mirror assembly.	1,275.00		
To painitng left mirror cover.	75.00		
To check electrical wiring systems	177.00		
Sundries.	40.00		
Total Labour 1:	1,567.00		
DESCRIPTION	QTY	PRIC	VALUE
LH OUTSIDE MIRROR COVER CAP PRIMED	1	128.10	128.10
RH HEATED OUTSIDE MIRROR	1	962.85	962.85
LH AUXILIARY MIRROR TURN INDICATOR	1	65.25	65.25
Total Parts :			1,156.20

	Labour 1	:	1,567.00
	Parts	:	1,156.20
	Labour 2	:	0.00
	Excess	:	0.00
	Total GST @ 7%	:	190.62
	Grand Total	:	2,913.82

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **