

BIKE PRODUCTION PTE LTD
610, Serangoon Road S(218216)
Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 19 Aug 2020

ASSESSMENT FOR REPAIR: HONDA CB150R MANUAL - FBP1493X

Chassis No.: MLHKC2882J5030348

Engine No.: KC32E0030348

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front fender	\$175.00 / SCR
1 pc	Front wheel shaft	\$75.00 ?
1 pc	Front disk brake	\$175.00 ?
1 pc	Front left fork assy	\$680.00 ?
1 pc	Front right fork assy	\$680.00 ?
1 pc	Steering stem	\$220.00 ?
1 pc	Steering bridge	\$195.00 ?
2 pcs	Steering bearings	\$90.00 ?
1 set	Steering bridge holder	\$150.00 ?
1 pc	Front left signal	\$145.00 / SCR
1 pc	Left view mirror	\$95.00 / SCR
1 pc	IU bracket	\$75.00 / SCR DEF
1 pc	Handle bar	\$175.00 / BT
1 pc	Left balancer	\$48.00 / BT
1 pc	Front headlamp	\$290.00 / SCR
1 pc	Front headlamp cover	\$105.00 / SCR
1 pc	Fuel tank left cover	\$295.00 XNL
1 pc	Radiator	\$385.00 ?
1 pc	Rear swing arm	\$485.00 XNL
		<hr/>
		\$4,538.00
	Less discount 10%	\$453.80
		<hr/>
		\$4,084.20
	<u>Special nett items</u>	
1 pc	Sport rim front	\$580.00 ?
1 pc	Coolant	\$50.00 ?
1 pc	Box rack	\$195.00 ?
1 pc	Top case	\$250.00 / SCR
1)	Towing charges	\$100.00 ?
	Replace, realign and adjust above	
	damaged parts, check wiring and	
2)	lighting system	\$800.00 300
	To knock, straighten chassis & body	
3)	balancing	\$380.00 XNL
	To remove/refit, replace (if damage) check and	
4)	straighten front fork tubes.	\$180.00 ?
	To remove/refit, replace (if damage) check and	
4)	straighten front sport rims.	\$150.00 ?
6)	Spray painting	\$280.00 150
	Total Estimate	<hr/> <hr/>
		\$7,049.20

Note: The above estimate is subjected to the prevailing GST of 7%

NA2 LK

20/8/2020 1330

L/S

3 DAYS

CHECK ITEM PHOTO

AFTER REPAIR PHOTO



For Bike Production Pte Ltd

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: