

Repair Estimate

Date : 24/8/2020

Reference: SLG2109D
TOYOTA /
Make: CAMRY 2.5
 AUTO

To Whom It May Concern

Dear Sir,

TP Budget Direct.
 Veron.

RE: VEHICLE : SLG2109D
CHASSIS NO.: MR053AK5004011434
ENGINE NO.: 2ARU338074

Name of insured : Tan Bak Leong
 Date of accident.: 18/08/2020

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)	
1	1	LHF Door <i>Dented</i>	\$ 941.30	✓
2	1	LHF Door Upper Hinge <i>3 new</i>	\$ 78.10	+
3	1	LHF Door Lower Hinge <i>3 new</i>	\$ 79.60	+
4	1	LHF Door Limiter <i>3 new</i>	\$ 92.50	+
5	1	LHF Door Striker <i>3 new</i>	\$ 79.60	+
6	1	LHF Door Inner Trim <i>3 new</i>	\$ 491.70	+
7	10	LHF Door Inner Trim Clips <i>3 new</i>	\$ 65.00	+
8	1	LHF Door Window Regulator With Motor <i>3 new</i>	\$ 171.30	+
9	1	LHF Door Window Regulator Motor <i>3 new</i>	\$ 326.80	+
10	1	LHR Door <i>Dented</i>	\$ 962.70	✓
11	1	LHR Door Upper Hinge <i>2</i>	\$ 78.10	+
12	1	LHR Door Lower Hinge <i>2</i>	\$ 79.60	+
13	1	LHR Door Limiter <i>2 new</i>	\$ 92.50	+
14	1	LHR Door Striker <i>2 new</i>	\$ 79.60	+
15	1	LHR Door Inner Trim <i>2 new</i>	\$ 491.70	+
16	1	LHR Door Inner Trim Clips <i>2 new</i>	\$ 65.00	+
17	1	LHR Door Window Regulator With Motor <i>3 new</i>	\$ 171.30	+
18	1	LHR Door Window Regulator Motor <i>3 new</i>	\$ 326.80	+
19	1	LHR Fender <i>Repis</i>	\$ 820.60	+
20	1	LH Rocker Panel <i>Repis</i>	\$ 524.10	+
21	1	Rear Windscreen <i>2 new</i>	\$ 1,210.80	+
22	1	Rear Windscreen Moulding <i>3 new</i>	\$ 95.30	+

1304
1428.

Parts Total: \$ 7,324.00
Less 25%: \$ 1,831.00
Total: \$ 5,493.00

Labour

Labour Description		Price (SGD)	
No.			
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 1,000.00	500
2	Carry out spray painting on accident affected area	\$ 1,400.00	900
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 60.00	30
4	To conduct transfer door mechanism to new door panel	\$ 160.00	✓
5	To apply door sealant to door	\$ 160.00	+
6	To remove and refit audio speaker	\$ 160.00	+
7	To conduct water leakage test after repairs of vehicle	\$ 80.00	+
8	To remove and refit rear windscreen due to replacement of rear fender	\$ 120.00	+

1590

Labour Total: \$ 3,140.00

Others

Other Description			Price (SGD)
No.	Qty		
0	0	NA	\$ -

Other Total: \$ -

GRAND TOTAL: \$ 8,633.00

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully



Service Advisor

Suhaimi

HP : 9189 2617 Email - aceautosolution@gmail.com

Adrian L
p/p 25/08/20.

APPROVER DETAILS

SURVEYOR : _____

CONTACT NO : _____

PART BY PART / LUMP SUM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

04 Days
total: 3018 (P/P)