

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel: 6631 1188

TOYOTA

Reg No : 196700086Z
Reg No : MR-8500000-9

ESTIMATE

Load "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No		Customer Detail		
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006/IC1111		Mr Matthias Yeo Chiew Leng (Yang Zhaolong) 124 Simei Street 1 #07-366 Singapore 520124 Mobile: 96898085		
Document No		0				
Document Date		20/08/2020				
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	
19	MMYQKT E4	NSP170R	13/01/2020	SJV3846Y	0	
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Order No/Remarks	
MHFZ28H3100067595	2NRX531956	60	Sam San Joi	20/08/2020 8.15	67/TP/SJV3846Y	
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI SUNDRIES TP CLAIM TP-SHC3155G ACC DATE:19/08/2020 DRIVE IN:20/08/2020 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				30.00
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON REAR ACCIDENT AREAS				183.18
3	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR				180.00
4	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST				160.00
5	Z	BP-SLANT SUPPLY SEALANT (NETT)- TAILGATE, REAR EN				360.00
6	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW DOO				462.00
7	B	BP-LAB2 REPLACE & INSTALL REAR WINDSCREEN GLASS				350.00
8	S	BP-SUBLET INSTALL REAR WINDSCREEN GLASS 3M SOLAR F				180.00
9	B	BP-LAB2 REMOVE & INSTALL REAR REVERSE CAMERA				720.00
10	B	BP-LAB2 REMOVE & INSTALL REAR SEAT, CARPET, GARNIS H AND TRIMMING TO ASSIST REPAIR				
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						
For or on behalf of Borneo Motors		Customer's Signature		Change Summary		Total
		Please acknowledge receipt of vehicle		Parts 20/8/20, 3-00pm Labour 9 days Materials PIP Lubrication/Fluid Others		Less
		Steve (LKK) 8322 8813 Stevechen@1kkauto.com		Ry Beh SPY		Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4221553

4221553

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 20/08/2020
TIME 09:05

VEHICLE NO SJV3846Y

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

TOYOTA

No : 196700086Z
Reg No : MR-8500000-9

ESTIMATE

Load "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:

www.toyota.com.sg

Toyota Bodycare Centre

17 Ubi Road 4

Singapore 409611

Tel no.: 6631 1188

Account Detail		Account No		Customer Detail	
India International Insurance P L 64 Cecil Street #06-02 10B Building Singapore 049111 Attn: Motor Claims Dept		S1000006 / IC1111		Mr Matthias Yeo Chiam Leng (Yang Zhaolong) 124 Simai Street 1 #07-366 Singapore 520124	
		Document No		0	
		Document Date		20/08/2020	
				Mobile: 96898085	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	MYVQNT E4	NSP170R	13/01/2020	SJV3846Y	0	20248	67/TP/SJV3846Y

Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On
MHFZ26H3100067595	2NRX531956	60	Sam San Joi	20/08/2020 8.15	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	B	BP-LAB2 REPAIR & REALIGN REAR RH CHASSIS PANEL				(phb) 720.00
12	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
13	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS 720 x 5				3600 5040.00
14	B	BP-RES2 STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				2360 3540.00
		RESPRAY JOB ON REAR ACCIDENT AFFECTED AR 590 x 4				
15	1	S52159-OU919 COVER, RR BUMPER, L/	1.00	316.10		316.10
16	2	S52156-OD100 SUPPORT, RR BUMPER S	1.00	73.60		73.60
17	3	S52576-OD270 RETAINER, RR BUMPER	1.00	70.50		70.50
18	4	S52155-OD110 SUPPORT, RR BUMPER S	1.00	73.60		73.60
19	5	S52575-OD280 RETAINER, RR BUMPER	1.00	70.50		70.50
20	6	S52161-OK040 CLIPS	10.00	4.10		41.00
21	7	S52151-OD010 EXTENSION, RR BUMPER	1.00	190.00		190.00
22	8	S52161-OD070 EXTENSION, RR BUMPER	1.00	129.10		129.10
23	9	S58307-OD320 PANEL SUB-ASSY, BODY	1.00	433.60		433.60
24	0	S58302-OD010 PANEL SUB-ASSY, LWR	1.00	696.30		696.30
25	1	S58311-OD902 PAN, RR FLOOR, L/BOL	1.00	698.70		698.70
26	2	S57601-OD390 MEMBER SUB-ASSY, RR	1.00	1464.90		1464.90
27	3	S64716-OD170 CO COVER, DECK TRIM, RR	1.00	154.10		154.10
28	4	S64421-OD010 TRAY, LUGGAGE COMPAR	1.00	323.10		323.10

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

4221554

PLEASE TEAR ALONG PERFORATED LINE

4221554

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SJV3846Y

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchcape

Borneo Motors

TOYOTA

No : 196700086Z
 g No : MR-8500000-9

ESTIMATE

load "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:

www.toyota.com.sg

Toyota Bodycare Centre

17 Ubi Road 4

Singapore 409611

Tel no.: 6631 1188

Account Detail

India International Insurance P L
 64 Cecil Street
 #06-02 IOB Building
 Singapore 049711
 Attn: Motor Claims Dept

Account No

S1000006/IC1111

Document No

0

Document Date

20/08/2020

Customer Detail

Mr Matthias Yeo Chiow Leng (Yang Zhaolong)
 124 Simei Street 1
 #07-366
 Singapore 520124
 Mobile: 96898085

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	MMYQKT	E4	NSP170R	13/01/2020	SJV3846Y	0	20248 67/TP/SJV3846Y
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MHE228H3100067595	2NRX531956	60	Sam San Joi	20/08/2020	8.15	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
29	5	S58408-0D010 CO BOARD SUB-ASSY, DECK <i>X ? (R4)</i>	1.00	155.60		155.60
30	6	S64730-0D400 CO PANEL ASSY, DECK TRI <i>X</i>	1.00	627.00		627.00
31	7	S67005-0D360 PANEL SUB-ASSY, BACK <i>/ DD</i>	1.00	1131.90		1131.90
32	8	S67881-0D130 WEATHERSTRIP, BACK D <i>/ CRU</i>	1.00	372.30		372.30
33	9	S67751-0D060 CO BOARD, BACK DOOR TRI <i>?</i>	1.00	190.00		190.00
34	0	T90467-08186 C3 CLIP <i>/ n/c</i>	10.00	2.40		24.00
35	1	S68105-0D261 GLASS SUB-ASSY, BACK <i>/ n/c</i>	1.00	1029.30		1029.30
36	2	S69350-0D240 LOCK ASSY, BACK DOOR <i>/ found</i>	1.00	467.60		467.60
37	3	S69430-0D090 STRIKER ASSY, BACK D <i>X</i>	1.00	25.70		25.70
38	4	T90975-02086 FRONT BONNET EMBLEM, <i>(Rear) / n/c</i>	1.00	72.20		72.20
39	5	S75442-0D290 PLATE, BACK DOOR NAM <i>/ n/c</i>	1.00	35.50		35.50
40	6	S75441-0D070 PLATE, BACK DOOR NAM <i>/ n/c</i>	1.00	53.20		53.20
41	7	T89997-30100 ANTENNA, ELECTRICAL <i>?</i>	1.00	72.00		72.00
42	8	T81480-52070 LAMP ASSY, RR FOG, <i>?</i>	1.00	234.30		234.30
43	9	T81481-52560 BRACKET, FOG LAMP <i>?</i>	1.00	55.90		55.90
44	0	T04562-12010 FRT W/SCREEN DAM KIT, <i>(Rear) / n/c</i>	1.00	121.00		121.00
45	1	T21000-20 SIKA 182010 SIKA TACK GO! (BLA <i>/ n/c</i>	1.00	108.00		108.00
46	2	T21000-22 SIKA 207. G+P ADHESIVE PRIMER <i>/ n/c</i>	1.00	200.00		200.00
47	3	SPC507-0D014 17 BACK SENSOR (1D4, SILVER ME) <i>/ DR</i>	1.00	172.40		172.40

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 9,883.00 Labour 11,752.00 Materials 533.18 Lubrication/Fluid 0.00 Others 0.00	22,168.18
			GST 7.00%
			Less 0.00
			Amount Due 23,719.95

LKK Auto Consultants hence notify

the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

PLEASE TEAR ALONG PERFORATED LINE

4221555

4221555

DATE 20/08/2020
 TIME 09:05

Acknowledged by Repairer SJV3846Y

Signature:

CUSTOMER

SIGNATURE

FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchape

Borneo Motors