



o Reg No : 196700086Z
iST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006/ICIIII1 Document No 0 Document Date 20/08/2020	Mr Matthias Yeo Chiow Leng (Yang Zhaolong) 124 Simei Street 1 #07-366 Singapore 520124 Mobile: 96898085

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	MWYQKT	E4	NSP170R	13/01/2020	SJV3846Y	0	20248 67/TP/SJV3846Y
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MHFZ28H3100067595	2NRX531956	60	Sam San Joi	20/08/2020	8.15	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI SUNDRIES TP CLAIM TP-SHC3155G ACC DATE:19/08/2020 DRIVE IN:20/08/2020 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30.00
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON REAR ACCIDENT AREAS				183.18
3	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR				180.00
4	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST				180.00
5	Z	BP-SLANT SUPPLY SEALANT (NETT)- TAILGATE, REAR EN D PANEL				160.00
6	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW DOO R				360.00
7	B	BP-LAB2 REPLACE & INSTALL REAR WINDSCREEN GLASS				462.00
8	S	BP-SUBLET INSTALL REAR WINDSCREEN GLASS 3M SOLAR F ILM				350.00
9	B	BP-LAB2 REMOVE & INSTALL REAR REVERSE CAMERA				180.00
10	B	BP-LAB2 REMOVE & INSTALL REAR SEAT, CARPET, GARNIS H AND TRIMMING TO ASSIST REPAIR				720.00
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4221553

O SECURITY GUARD

4221553

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 20/08/2020
TIME 09:05

VEHICLE NO SJV3846Y

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

**Borneo Motors**



Reg No : 196700086Z
ST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006/ICIIII1	Mr Matthias Yeo Chiow Leng (Yang ZhaoLong) 124 Simei Street 1 #07-366 Singapore 520124 Mobile: 96898085
	Document No 0	
	Document Date 20/08/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	MWYQKT	E4	NSP170R	13/01/2020	SJV3846Y	0	20248 67/TP/SJV3846Y
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
WHFZ28H3100067595	2NRX531956	60	Sam San Joi	20/08/2020	8.15	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	B	BP-LAB2 REPAIR & REALIGN REAR RH CHASSIS PANEL				720.00
12	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
13	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS				5040.00
		STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				
14	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AR				3540.00
		EAS				
15	1	S52159-OU919 COVER, RR BUMPER, L/	1.00	316.10		316.10
16	2	S52156-OD100 SUPPORT, RR BUMPER S	1.00	73.60		73.60
17	3	S52576-OD270 RETAINER, RR BUMPER	1.00	70.50		70.50
18	4	S52155-OD110 SUPPORT, RR BUMPER S	1.00	73.60		73.60
19	5	S52575-OD280 RETAINER, RR BUMPER	1.00	70.50		70.50
20	6	S52161-OK040 CLIPS	10.00	4.10		41.00
21	7	S52151-OD010 EXTENSION, RR BUMPER	1.00	190.00		190.00
22	8	S52161-OD070 EXTENSION, RR BUMPER	1.00	129.10		129.10
23	9	S58307-OD320 PANEL SUB-ASSY, BODY	1.00	433.60		433.60
24	0	S58302-OD010 PANEL SUB-ASSY, LWR	1.00	696.30		696.30
25	1	S58311-OD902 PAN, RR FLOOR, L/BOL	1.00	698.70		698.70
26	2	S57601-OD390 MEMBER SUB-ASSY, RR	1.00	1464.90		1464.90
27	3	S64716-OD170 CO COVER, DECK TRIM, RR	1.00	154.10		154.10
28	4	S64421-OD010 TRAY, LUGGAGE COMPAR	1.00	323.10		323.10

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4221554

TO SECURITY GUARD

4221554

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 20/08/2020
TIME 09:05

VEHICLE NO SJV3846Y

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



Reg No : 196700086Z
ST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006/ICIIII1	Mr Matthias Yeo Chiow Leng (Yang ZhaoJong) 124 Simei Street 1 #07-366 Singapore 520124 Mobile: 96898085
	Document No 0	
	Document Date 20/08/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	MWYQKT	E4	NSP170R	13/01/2020	SJV3846Y	0	20248 67/TP/SJV3846Y
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MHFZ28H3100067595	2NRX531956	60	Sam San Joi	20/08/2020	8.15 --/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
29	5	S58408-0D010 C0 BOARD SUB-ASSY, DECK	1.00	155.60		155.60
30	6	S64730-0D400 C0 PANEL ASSY, DECK TRI	1.00	627.00		627.00
31	7	S67005-0D360 PANEL SUB-ASSY, BACK	1.00	1131.90		1131.90
32	8	S67881-0D130 WEATHERSTRIP, BACK D	1.00	372.30		372.30
33	9	S67751-0D060 C0 BOARD, BACK DOOR TRI	1.00	190.00		190.00
34	0	T90467-08186 C3 CLIP	10.00	2.40		24.00
35	1	S68105-0D261 GLASS SUB-ASSY, BACK	1.00	1029.30		1029.30
36	2	S69350-0D240 LOCK ASSY, BACK DOOR	1.00	467.60		467.60
37	3	S69430-0D090 STRIKER ASSY, BACK D	1.00	25.70		25.70
38	4	T90975-02086 FRONT BONNET EMBLEM,	1.00	72.20		72.20
39	5	S75442-0D290 PLATE, BACK DOOR NAM	1.00	35.50		35.50
40	6	S75441-0D070 PLATE, BACK DOOR NAM	1.00	53.20		53.20
41	7	T89997-30100 ANTENNA, ELECTRICAL	1.00	72.00		72.00
42	8	T81480-52070 LAMP ASSY, RR FOG,	1.00	234.30		234.30
43	9	T81481-52560 BRACKET, FOG LAMP	1.00	55.90		55.90
44	0	T04562-12010 FRT W/SCREEN DAM KIT,	1.00	121.00		121.00
45	1	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	1.00	108.00		108.00
46	2	T21000-22 SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00
47	3	SPC507-0D014 17 BACK SENSOR (1D4, SILVER ME)	1.00	172.40		172.40

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 9,883.00 Labour 11,752.00 Materials 533.18 Lubrication/Fluid 0.00 Others 0.00	22,168.18 GST 7.00% 1,561.77 Less 0.00 Amount Due 23,719.95

PLEASE TEAR ALONG PERFORATED LINE

4221555

TO SECURITY GUARD

4221555

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 20/08/2020
TIME 09:05

VEHICLE NO SJV3846Y

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

**Borneo Motors**

CUSTOMER