



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS

ELROKARS GROUP

PORSCHE

INDIA INT'L INSURANCE PTE LTD		NAME : Tang Wee Houe		WIP : 62266	
64 CECIL STREET #04-05		ADDRESS : 28 Bukit Tunggul Road		EXCESS :	
IOB BUILDING		Singapore 309721		DATE: 19-Aug-20	
SINGAPORE 049711		TEL :			
ATTN : MOTOR CLAIMS					
FAX :					
VEH NO :	SDG8710Y	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WPQZZZ98Z1S600433	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY
MODEL :	986 BOXSTER TIPTRONIC	DATE REG.:	5-Jan-01	POLICY NO. :	
NATURE OF WORKS					
S/NO	Parts Description			REVISED	PRICES
	QTY				
1	FRONT FENDER RH	1	P996-503-032-04-GRV	bt ✓	\$ 1,225.40
2	SPEED NUT	11	P999-507-003-01-	rel ✓	\$ 17.60
3	FRONT RH FENDER COVER	1	P996-504-642-01-01C	?	\$ 20.90
4	RIVET	3	P999-591-712-40-	rel ✓	\$ 4.80
5	PROTECTIVE FILM RH	1	P996-504-532-00-	rel ✓	\$ 20.20
6	FRONT RH FENDER STRUT BAR	1	P996-504-441-00-GRV	?	\$ 68.80
7	FRONT FENDER BRACKET	1	P996-504-555-00-GRV	?	\$ 28.20
8	HEXAGON NUT	6	P900-377-010-01-	rel ✓	\$ 9.60
9	FRONT BUMPER	1	P986-505-311-07-	Ry	\$ 1,917.00
10	FRONT BUMPER TOWING COVER	1	P964-505-103-00-G2X	X	\$ 37.40
11	FRONT BUMPER RETAINER RH	1	P996-505-536-00-	X	\$ 113.20
12	BRACKET- RETAINING STRIP FRT BPR RH	1	P996-505-540-00-	X	\$ 92.90
13	RHS MIRROR HOUSING	1	P996-731-620-00-G2L	cr1 ✓	\$ 242.20
14	MIRROR BASE RIGHT ELECTRIC	1	P996-731-220-03-G2L	?	\$ 633.90
15	TRIM .SIDE MIRROR RH	1	P996-731-720-00-G2L	cr1 ✓	\$ 22.40
16	MIRROR ADJUSTING MOTOR	1	P996-624-048-00-	?	\$ 329.00
17	FILLER PIECE OUTER RH	1	P996-537-732-00-	X	\$ 35.10
18	FILLER PIECE INNER RH	1	P996-537-734-00-	X	\$ 24.60
19	MIRROR GLASS (6678)	1	P996-731-036-02-	X	\$ 272.40
20	FRONT RH SIGNAL LIGHT	1	P996-631-034-03-	cut ✓	\$ 128.60
21	SHOCK ABSORBER RH	1	P986-343-041-23-	?	\$ 1,495.00
22	FRT ABSORBER STOPPER	1	P996-343-301-02-	?	\$ 60.10
23	DEEP-GROOVE BALL BEARING W	1	P996-343-515-05-	?	\$ 114.10
24		0	0		\$ -
TOTAL PARTS					\$ 6,913.40
LESS 10%					\$ 691.34
TOTAL PARTS COST					\$ 6,222.06
Labour Description					
1	TO REMOVE /INSTALL FRT BUMPER. FRT FENDER RH, RH SIDE MIRROR & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR FRONT DOOR RH & ALL AREAS AFFECTED BY THE ACCIDENT.			4680	\$ 6,240.00

2	TO RESPRAY FRT BUMPER, FRT FENDER RH, FRT DOOR RH, RH SIDE MIRROR RH.	3750	\$ 4,600.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.	200	\$ 250.00
4	TO REMOVE & REPLACE THE FRONT SUSPENSION RH	NETT ?	\$ 1,560.00
5	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT. <i>Report</i>	NETT ?	\$ 680.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	200	\$ 250.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT ✓	\$ 600.00
8	SUNDRIES.	NETT 20	\$ 50.00
TOTAL LABOUR		\$ -	\$ 14,230.00
TOTAL PARTS		\$ -	\$ 6,222.06
TOTAL		\$ -	\$ 20,452.06
LESS EXCESS		\$ -	\$ -
TOTAL AFTER EXCESS		\$ -	\$ -
GST 7%		\$ -	\$ -
GRAND TOTAL		\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Tanflin 97445749 / 67418451

21/8/2011

06 days

Resurvey before paint

Tanflin Insurance

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: