

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III20008736/R1ES3Q2  
**Date:** 27/10/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant Vehicle No :</b>	FU8814J	<b>Insured Vehicle No :</b>	SHA6022Y
Date of Loss:	07/08/2020	Nature of Claim:	TP
		Claim No:	MCT20080135

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>FU8814J</b>	Engine No:	NF125MDE0011232
Make & Model:	HONDA NF125MD, 125cc	Chassis No:	NF125MD0011232
Reg. Date:	03/05/2002 (Man. Year: 2002)	Odometer:	0 km
Colour:	Red		
Engine Capacity:	125 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	70/90-17	Rear Tyre Size:	70/90-17
Front Left Side:	Michelin 3 mm	Rear Left Side:	Michelin 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,763.60	1,108.40	655.20	37.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	280.00	230.00	50.00	17.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,043.60</b>	<b>1,338.40</b>	<b>705.20</b>	<b>34.51</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,050.00</b>		

(S\$)	2,043.60	1,050.00	993.60	48.62
<b>+ GST 7.00/7.00% (S\$)</b>	143.05	73.50	69.55	48.62
<b>Nett Amount (S\$)</b>	<b>2,186.65</b>	<b>1,123.50</b>	<b>1,063.15</b>	<b>48.62</b>
<b>+ Loss of Use (3.0 x S\$30.00/day) (S\$)</b>		90.00		
<b>Nett Liability (S\$)</b>		<b>1,213.50</b>		

INSPECTION

Date of Assignment: 20/08/2020

Date Inspected: 20/08/2020

Estimated Period of Repair: 3.0 days

Inspected At: Southern Motor (HQ)  
BLK 1006 BUKIT MERAH LANE 2, #01-10  
Singapore 159762**Adjuster:** MOHD RASUL**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 11 Oct 2021)	
<b>Parts:</b>	N/A	HONDA NF125MD 125cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FU8814J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP	Scratched	55.00 FL	*55.00 FL
2	1		*FRONT SIGNAL LIGHT	Serviceable	45.00 FL	*- FL
3	1		*HANDLE BAR	Serviceable	48.00 FL	*- FL
4	1		*FRONT FORK COMPLETE	Bent	320.00 FL	*320.00 FL
5	1		*MIRROR	Scratched	25.00 FL	*25.00 FL
6	1		*SET BODY	Scratched	280.00 FL	*280.00 FL
7	1		*FRONT BRAKE SHOE PUMP	Serviceable	160.00 FL	*- FL
8	1		*FRON BRAKE DISC	Serviceable	65.00 FL	*- FL
9	1		*FRONT SPORT RIM	Serviceable	165.00 FL	*- FL
10	1		*CLUTCH COVER	Scratched	68.00 FL	*68.00 FL
11	1		*FRONT FOOTREST	Bent	35.00 FL	*35.00 FL
12	1		*REAR FOOTREST	Scratched	15.00 FL	*15.00 FL
13	1		*FOOTREST BRACKET	Bent	43.00 FL	*43.00 FL
14	1		*EXHAUST PIPE	Serviceable	215.00 FL	*- FL
15	1		*FRONT MUDGUARD	Scratched	35.00 FL	*35.00 FL
16	1		*IU	Cracked	165.00 FS	*165.00 FS
17	1		*ENGINE OIL	Not Necessary	15.00 FS	*- FS
18	1		*GASKET	Not Necessary	12.00 FS	*- FS
19	1		*REAR BOX	Scratched	90.00 FS	*90.00 FS
20	1		*STEERING CONE	Necessary	65.00 FS	*65.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>1,921.00</b>	<b>1,196.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	157.40	87.60
<b>Total Parts (S\$)</b>	<b>1,763.60</b>	<b>1,108.40</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORT	New	30.00	30.00
2	LABOUR	New	250.00	200.00
Gross Labour Cost (S\$)			280.00	230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >