

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

20-Aug-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6073 P

1 pc	Front bumper	\$	531.00 <i>de</i>
1 pc	Front bumper emblem	\$	44.00 <i>re</i>
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00	16.	\$ <i>o/s</i> X <i>n/s</i> 32.00 <i>o/s de</i>
1 pc	n/s headlamp	\$	1,028.00 <i>o/s</i>
1 pc	Front bumper n/s fog lamp cover	\$	66.00 X <i>n/s</i>
1 pc	Front bumper o/s & n/s protector	20.50. <i>n/s de</i>	\$ <i>o/s</i> X 51.00 <i>o/s de</i>
1 pc	Front n/s wheel house	\$	464.00 <i>R</i>
1 pc	Front n/s fender	\$	384.00 <i>bt</i>
1 pc	Front n/s fender moulding	\$	34.00 <i>de</i>
1 pc	Front n/s fender inner shield	\$	120.00 <i>tu</i>
1 pc	Front n/s wheel cover	\$	116.00 <i>n/s</i>
1 pc	Front n/s rim	\$	246.00 <i>bt</i>
1 pc	Cross member	\$	789.00 X <i>n/s</i>
1 pc	Front n/s driveshaft	\$	894.00 X <i>n/s</i>
1 pc	Front steering rack	\$	866.00 X <i>n/s</i>
1 pc	Front n/s lower arm	\$	439.00 <i>bt</i>
1 pc	Front n/s tie rod end	\$	61.00 X <i>n/s</i>
1 pc	Front n/s shock absorber	\$	330.00 <i>?bt</i>
1 pc	Front n/s ball joint	\$	59.00 <i>?bt</i>
1 pc	Front n/s knuckle arm	\$	547.00 <i>bt</i>
1 pc	Front n/s knuckle bearing	\$	157.00 <i>bt</i>
1 pc	Front n/s stabilizer link	\$	86.00 <i>?bt</i>
1 pc	Front n/s insulator assy strut	\$	105.00 <i>?de X n/s</i>
1 pc	Front n/s door	\$	791.00 <i>R</i>
2 pcs	Front n/s door hinges @ \$34.00	\$	68.00 <i>R</i>
1 pc	n/s mirror Assy	\$	590.00 <i>R</i>
1 pc	n/s rocker panel garnish	\$	286.00 <i>de</i>
		\$	9,184.00
		\$	918.40
		\$	8,265.60

4443.50
10/4 3999.15

Less 10%

S/NETT

1 pc	Front bumper clips	\$	30 48.00 <i>re</i>
1 pc	Front n/s fender sticker	\$	30.00 <i>re</i>
1 set	Front n/s fender inner shield clips	\$	28.00 <i>re</i>
1 set	n/s door stickers	\$	100.00 <i>re</i>

20-Aug-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6073 P

1 set	n/s rocker panel garnish clips	\$ 38.00 <i>na</i>
1 pc	Front n/s tyre	<i>160</i> \$ <i>80%</i> 200.00 <i>put on</i>
	Towing fee	\$ 50.00 ✓
	Sundry	\$ 50.00 <i>20</i>
	To check front n/s wheel alignment	\$ 80.00 ✓
	To check for wiring and to focus head lamps	\$ 60.00 <i>30</i>
	To dismantle / refit front n/s wheel undercarriage	\$ 250.00 <i>150 photo</i>
	To dismantle and refit front n/s door inner components onto new shell door	\$ 150.00 <i>X na</i>
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 <i>60</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	<i>800</i> \$ 1,600.00
	To putty and spray painting on bonnet, front bumper, front n/s fender, front n/s windscreen pillar, front n/s door, n/s rocker panel garnish, rear n/s door, front n/s wheel house, n/s mirror cover, n/s rocker panel	<i>1200</i> \$ 1,800.00
	To apply rustproofing on the repaired and replaced panels.	<i>30</i> \$ 150.00
		<u>\$ 13,079.60</u> <i>2806</i>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Tanpin 9-779 5749
WP' 20/8/20 @ 430pm
Lumpsum
Repair after repair
06 days
terfiri @ 11/11/2020

3999.15
2806
6805.15
1/5 \$5400
6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey to the after spray painting
- To display damaged parts during resurvey
- Parts prices subject to confirmation
- Third party survey on "Without Prejudice" basis
- No litigation to be allowed
- Supplemental survey may be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: