

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

20-Aug-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6073 P

1 pc	Front bumper	\$ 531.00 <i>de</i>
1 pc	Front bumper emblem	\$ 44.00 <i>re</i>
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00	\$ <i>o/s</i> X 32.00 <i>n/s de</i>
1 pc	n/s headlamp	\$ 1,028.00 <i>o/s</i>
1 pc	Front bumper n/s fog lamp cover	\$ 66.00 X
1 pc	Front bumper o/s & n/s protector	<i>n/s de</i> ✓ \$ <i>o/s</i> X 51.00 <i>o/s</i> <i>de</i>
1 pc	Front n/s wheel house	\$ 464.00 <i>Rx</i>
1 pc	Front n/s fender	\$ 384.00 <i>bt</i>
1 pc	Front n/s fender moulding	\$ 34.00 <i>de</i>
1 pc	Front n/s fender inner shield	\$ 120.00 <i>tu</i>
1 pc	Front n/s wheel cover	\$ 116.00 <i>mis</i>
1 pc	Front n/s rim	\$ 246.00 <i>bt</i>
1 pc	Cross member	\$ 789.00 X
1 pc	Front n/s driveshaft	\$ 894.00 ?
1 pc	Front steering rack	\$ 866.00 X
1 pc	Front n/s lower arm	\$ 439.00 <i>bt</i>
1 pc	Front n/s tie rod end	\$ 61.00 ?
1 pc	Front n/s shock absorber	\$ 330.00 ?
1 pc	Front n/s ball joint	\$ 59.00 ?
1 pc	Front n/s knuckle arm	\$ 547.00 <i>bt</i>
1 pc	Front n/s knuckle bearing	\$ 157.00 <i>bt</i>
1 pc	Front n/s stabilizer link	\$ 86.00 ?
1 pc	Front n/s insulator assy strut	\$ 105.00 ?
1 pc	Front n/s door	\$ 791.00 <i>Rx</i>
2 pcs	Front n/s door hinges @ \$34.00	\$ 68.00 <i>Rx</i>
1 pc	n/s mirror Assy	\$ 590.00 <i>Rx</i>
1 pc	n/s rocker panel garnish	\$ 286.00 <i>de</i>
		\$ 9,184.00
Less 10%		\$ 918.40
		\$ 8,265.60

S/NETT

1 pc	Front bumper clips	\$ 30 48.00 <i>re</i>
1 pc	Front n/s fender sticker	\$ 30.00 <i>re</i>
1 set	Front n/s fender inner shield clips	\$ 28.00 <i>re</i>
1 set	n/s door stickers	\$ 100.00 <i>re</i>

20-Aug-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6073 P

1 set	n/s rocker panel garnish clips	\$ 38.00 <i>new</i>
1 pc	Front n/s tyre	\$ 80% 200.00 <i>put new</i>
	Towing fee	\$ 50.00 ✓
	Sundry	\$ 50.00 <i>20</i>
	To check front n/s wheel alignment	\$ 80.00 ✓
	To check for wiring and to focus head lamps	\$ 60.00 <i>30</i>
	To dismantle / refit front n/s wheel undercarriage	\$ 250.00 <i>150 photo</i>
	To dismantle and refit front n/s door inner components onto new shell door	\$ 150.00 <i>X</i>
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 <i>60</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	\$ 800 1,600.00
	To putty and spray painting on bonnet, front bumper, front n/s fender, front n/s windscreen pillar, front n/s door, n/s rocker panel garnish, rear n/s door, front n/s wheel house, n/s mirror cover, n/s rocker panel	\$ 1200 1,800.00
	To apply rustproofing on the repaired and replaced panels.	\$ 30 150.00
		<u>\$ 13,079 60</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Tauphin 9-779 5749
WP 20/8/20 @ 430pm
Lumpsum
Resurvey after repair
06 days
terphi @ 1/11/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before later spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary repairs must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: