

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

20-Aug-20

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6073 P

1 pc	Front bumper	\$	531.00
1 pc	Front bumper emblem	\$	44.00
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00	\$	32.00
1 pc	n/s headlamp	\$	1,028.00
1 pc	Front bumper n/s fog lamp cover	\$	66.00
1 pc	Front bumper o/s & n/s protector	\$	51.00
1 pc	Front n/s wheel house	\$	464.00
1 pc	Front n/s fender	\$	384.00
1 pc	Front n/s fender moulding	\$	34.00
1 pc	Front n/s fender inner shield	\$	120.00
1 pc	Front n/s wheel cover	\$	116.00
1 pc	Front n/s rim	\$	246.00
1 pc	Cross member	\$	789.00
1 pc	Front n/s driveshaft	\$	894.00
1 pc	Front steering rack	\$	866.00
1 pc	Front n/s lower arm	\$	439.00
1 pc	Front n/s tie rod end	\$	61.00
1 pc	Front n/s shock absorber	\$	330.00
1 pc	Front n/s ball joint	\$	59.00
1 pc	Front n/s knuckle arm	\$	547.00
1 pc	Front n/s knuckle bearing	\$	157.00
1 pc	Front n/s stabilizer link	\$	86.00
1 pc	Front n/s insulator assy strut	\$	105.00
1 pc	Front n/s door	\$	791.00
2 pcs	Front n/s door hinges @ \$34.00	\$	68.00
1 pc	n/s mirror Assy	\$	590.00
1 pc	n/s rocker panel garnish	\$	286.00
		\$	9,184.00
		Less 10%	\$ 918.40
			\$ 8,265.60

### S/NETT

1 pc	Front bumper clips	\$	48.00
1 pc	Front n/s fender sticker	\$	30.00
1 set	Front n/s fender inner shield clips	\$	28.00
1 set	n/s door stickers	\$	100.00

20-Aug-20

**ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6073 P**

1 set	n/s rocker panel garnish clips	\$	38.00
1 pc	Front n/s tyre	\$	200.00
	Towing fee	\$	50.00
	Sundry	\$	50.00
	To check front n/s wheel alignment	\$	80.00
	To check for wiring and to focus head lamps	\$	60.00
	To dismantle / refit front n/s wheel undercarriage	\$	250.00
	To dismantle and refit front n/s door inner components onto new shell door	\$	150.00
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	\$	1,600.00
	To putty and spray painting on bonnet, front bumper, front n/s fender, front n/s windscreen pillar, front n/s door, n/s rocker panel garnish, rear n/s door, front n/s wheel house, n/s mirror cover, n/s rocker panel	\$	1,800.00
	To apply rustproofing on the repaired and replaced panels.	\$	150.00
		<u>\$</u>	<u>13,079.60</u>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

***THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.***