

Kang Car Repairers Pte Ltd

•1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Estimate No: **EST2000166**
Date: 19 Aug 2020

Veh Reg No: **SMP3356R**
Make/Model: TOYOTA VIOS 1.5E (AUTO)

Chasis No: MR2B23F3201180977
Reg. Date: 23/09/2019
Your Ref No: GBC39A

Claim Type: Third Party
Accident Date: 14/08/2020
TP Veh Reg No: GBC39A

Xiao Chun

Estimate Repair Cost to Vehicle No :SMP3356R

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC BONNET <i>Distorted</i>	837.70	✓
2	2 PCS BONNET HINGE <i>Best</i>	158.20	✓
3	1 PC BONNET TRIM <i>Cupled</i>	253.20	✓
4	2 PCS FRT BONNET WIPER NOZZLE <i>See see</i>	125.40	+
5	1 PC BONNET LOCK <i>Damaged</i>	105.90	✓
6	1 PC BONNET LOCK CABLE <i>Tampered</i>	55.10	✓
7	1 PC BONNET STAND <i>See</i>	78.20	+
8	1 PC BONNET STAND CLIP <i>See</i>	12.20	+
9	1 PC FRT BRACE PANEL <i>Best</i>	108.10	✓
10	2 PCS BONNET STOPPER <i>See</i>	16.00	+
11	1 PC FRT FENDER RH <i>Repaired Buckled</i>	743.20	✓
12	1 PC FRT FENDER INNER BRACKET <i>See</i>	123.10	+
13	1 PC FRT FENDER COWLING RH <i>See</i>	275.40	+
14	1 PC FRT FENDER LH <i>Buckled</i>	743.20	✓
15	1 PC FRT FENDER INNER BRACKET LH <i>See</i>	123.10	+
16	1 PC FRT FENDER COWLING LH <i>See</i>	275.40	+
17	1 PC FRT SUPPORT PANEL <i>Distorted</i>	978.70	✓
18	1 PC FRT SUPPORT PANEL TOP SENSOR <i>could</i>	199.90	✓
19	1 PC FRT SUPPORT PANEL TOP SENSOR COVER <i>Deformed</i>	34.30	✓
20	1 PC FRT SUPPORT PANEL TOP TRIM <i>could</i>	181.40	✓
21	1 PC FRT GRILLE <i>smashed</i>	279.10	✓
22	1 PC FRT BUMPER RUBBER <i>ut</i>	39.80	✓
23	1 PC FRT GRILLE EMBLEM <i>See</i>	69.70	✓
24	1 PC FRT GRILLE EMBLEM BASE <i>could</i>	128.20	✓
25	1 PC HEADLAMP RH <i>could</i>	1,144.90	✓
26	1 PC HEADLAMP PANEL RH <i>Buckled</i>	95.50	✓
27	1 PC HEADLAMP LH <i>could</i>	1,144.90	✓
28	1 PC HEADLAMP PANEL LH <i>Buckled</i>	95.50	✓
29	1 PC FRT BUMPER <i>Distorted</i>	492.90	✓

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TTL 6747 7636 FAX 6748 5071 Email kangcar@singnet.com.sg
GST 201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909
TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Estimate No: EST2000166
Date: 19 Aug 2020

Veh Reg No: SMP3356R
Make/Model: TOYOTA VIOS 1.5E (AUTO)

Chasis No: MR2B23F3201180977

Reg. Date: 23/09/2019

Your Ref No: GBC39A

Claim Type: Third Party
Accident Date: 14/08/2020
TP Veh Reg No: GBC39A

Estimate Repair Cost to Vehicle No :SMP3356R

Quantity	Description	List Price	Amount
		SS	SS
30	1 PC FRT BUMPER REINFORCEMENT <i>Best</i>	372.40 ✓	
31	2 PCS FRT BUMPER SIDE RETAINER <i>new</i>	189.40 ✓	
32	1 PC FRT BUMPER INNER TOP GARNISH <i>could</i>	165.70 ✓	
33	1 PC FRT BUMPER GRILLE <i>could</i>	228.80 ✓	
34	2 PCS FRT BUMPER SIDE GARNISH <i>could</i>	84.60 ✓	
35	1 PC FRT FOG LAMP RH <i>new</i>	312.20 +	
36	1 PC FRT FOG LAMP COVER RH <i>new</i>	95.30 +	
37	1 PC FRT FOG LAMP LH <i>could</i>	312.20 ✓	
38	1 PC FRT FOG LAMP COVER LH <i>could</i>	95.30 ✓	
39	1 PC HORN <i>new</i>	140.60 ✓	
40	1 PC FRT HORN BRACKET <i>Best</i>	49.60 ✓	
41	1 PC AIR CONDENSER SIDE COVER <i>could</i>	105.40 ✓	
42	1 PC AIRCON CONDENSER <i>Best</i>	1,054.80 ✓	
43	1 PC AIRCON CONDENSER RH SIDE GARNISH <i>could</i>	82.70 ✓	
44	1 PC AIRCON CONDENSER LH SIDE GARNISH <i>could</i>	62.70 ✓	
45	1 PC AIRCON COMPRESSOR <i>new</i>	1,293.70 +	
46	1 PC AIRCON SUCTION PIPE <i>new</i>	473.70 +	
47	1 PC AIRCON DISCHARGE PIPE <i>Best</i>	364.70 +	
48	1 PC AIRCON RECEIVER PIPE	413.60 ✓	
49	1 PC AIRCON LIQUID PIPE	512.40 +	
50	1 PC RADIATOR FAN MOTOR ASSY <i>new</i>	691.30 ✓ 428.	
51	1 PC RADIATOR FAN COWLING <i>could</i>	244.50 ✓	
52	1 PC RADIATOR FAN SIDE PANEL <i>new</i>	98.20 X	
53	1 PC RADIATOR <i>could</i>	1,740.50 ✓	
54	1 PC RADIATOR TOP HOSE <i>new</i>	42.20 +	
55	1 PC RADIATOR BOTTOM HOSE <i>new</i>	43.60 X	
56	1 PC RADIATOR UNDER COVER RH <i>new</i>	209.30 ✓	
57	1 PC RADIATOR UNDER COVER LH <i>new</i>	139.60 ✓	
58	2 PCS RADIATOR TOP BUSS <i>new</i>	25.60 ✓	
59	2 PCS RADIATOR BOTTOM BUSS <i>new</i>	25.60 ✓	

1pc manifold oxygen sensor *Best* ✓

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Estimate No: **EST2000166**
Date: 19 Aug 2020

Veh Reg No: **SMP3356R**
Make/Model: TOYOTA VIOS 1.5E (AUTO)

Chasis No: MR2B23F3201180977

Reg. Date: 23/09/2019

Your Ref No: GBC39A

Claim Type: Third Party
Accident Date: 14/08/2020
TP Veh Reg No: GBC39A

Estimate Repair Cost to Vehicle No :SMP3356R

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
60	1 PC FRT WIPER TANK <i>seen</i>	113.80	✓
61	1 PC FRONT WIPER TANK MOTOR <i>seen</i>	434.10	✓
62	1 PC AIR CLEANER <i>checked</i>	935.90	✓
63	1 PC AIR CLEANER JOINT HOSE <i>seen</i>	82.70	✓
64	1 PC AIR CLEANER OUTLET HOSE <i>Deled</i>	122.10	✓
65	1 PC FRT INTAKE MANIFOLD <i>seen</i>	978.90	✓
66	1 PC FRT EXHAUST MANIFOLD COVER <i>Deled</i>	100.70	✓
67	1 PC ALTERNATOR <i>seen</i>	2,306.10	✓
68	1 PC FRT WIPER PANEL GARNISH <i>at</i>	644.00	✓
69	2 PCS FRT WIPER PANEL SIDE GARNISH <i>LH Deled, RH Missing</i>	116.60	✓
70	1 PC FRT WINDSCREEN GLASS <i>checked</i>	1,669.70	✓
71	1 PC DASHBOARD <i>torn</i>	1,411.80	✓
72	1 PC FRT STEERING AIRBAG <i>Activated</i>	3,206.80	✓
73	1 PC FRT STEERING LOWER AIR BAG <i>Activated</i>	1,861.90	✓
74	1 PC FRT STEERING LOWER AIR BAG COVER <i>torn</i>	332.70	✓
75	1 PC DASHBOARD LH AIRBAG <i>Activated</i>	2,354.10	✓
76	2 PCS FRT WINDSCREEN INNER SIDE GARNISH <i>seen</i>	355.20	✓
77	1 PC ROOF RH AIR BAG <i>Activated</i>	1,898.20	✓
78	1 PC ROOF LH AIR BAG <i>Activated</i>	1,898.20	✓
79	1 PC FRT UPHOLSTERY <i>sampled</i>	1,991.40	✓
80	2 PCS FRT UPHOLSTERY HANDLE <i>seen</i>	336.60	✓
81	1 UNIT FRT RH SEAT BELT <i>Activated</i>	842.50	✓
82	1 PC FRT RH SEAT BELT COVER <i>seen</i>	187.30	✓
83	1 PC FRT LH SEAT BELT <i>Activated</i>	842.50	✓
84	1 PC FRT LH SEAT BELT COVER <i>Activated + seen</i>	187.30	✓
85	1 PC FRT STEERING AIRBAG SENSOR <i>Activated</i>	327.80	✓
86	1 PC DASHBOARD LH AIR BAG SENSOR <i>Activated</i>	327.80	✓
87	1 PC AIR BAG CONTROL UNIT <i>Activated</i>	1,506.40	✓
88	1 PC BOOT LID <i>Distorted</i>	855.50	✓
89	1 PC BOOTLID LOGO <i>seen</i>	52.20	✓

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S: CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Estimate No: **EST2000166**
Date: 19 Aug 2020

Veh Reg No: **SMP3356R**
Make/Model: TOYOTA VIOS 1.5E
(AUTO)

Chasis No: MR2B23F3201180977
Reg. Date: 23/09/2019
Your Ref No: GBC39A

Claim Type: Third Party
Accident Date: 14/08/2020
TP Veh Reg No: GBC39A

Estimate Repair Cost to Vehicle No :SMP3356R

Quantity	Description	List Price	Amount
		SS	SS
90	1 PC BOOT LID "VIOS" EMBLEM } <i>Nec</i>	43.60 ✓	
91	1 PC BOOTLID "E" EMBLEM	38.60 ✓	
92	2 PCS BOOT LID HINGE <i>Hinge Best</i>	190.40 ✓	
93	2 PCS REAR DOOR HINGE SPRINGS <i>new</i>	205.40 +	
94	1 PC BOOT LID LAMP LH } <i>cracked</i>	179.80 ✓	
95	1 PC BOOT LID LAMP RH } <i>cracked</i>	179.80 ✓	
96	1 PC REAR NUMBER PLATE LAMP GARNISH <i>Del'd</i>	130.30 ✓	
97	2 PCS REAR NUMBER PLATE LAMP <i>new</i>	125.80 ✓	
98	1 PC BOOT LID OUTER LOCK BUTTON <i>Del'd</i>	228.40 ✓	
99	1 PC BOOTLID INNER LOCK <i>Del'd</i>	320.40 ✓	
100	1 PC BOOT LID INNER LOCK CHECKER <i>Best.</i>	38.90 ✓	
101	1 PC BOOT LID TRIM <i>Del'd</i>	278.90 ✓	
102	2 PCS BOOTLID STOPPER <i>new</i>	32.00 +	
103	1 PC REAR BOOT LID LOCK CABLE <i>new</i>	108.30 +	
104	1 PC BOOTLID RUBBER <i>At</i>	166.40 ✓	
105	1 PC REAR FENDER RH <i>Buckled.</i>	892.10 ✓	
106	1 PC REAR FENDER TRIM RH <i>cracked</i>	355.90 ✓ 258	
107	1 PC REAR FENDER MUDFLAP RH <i>new</i>	76.90 +	
108	1 PC REAR FENDER DRAIN PANEL <i>Regis</i>	143.00 +	
109	1 PC REAR FENDER VENTILATION COVER <i>new</i>	65.60 +	
110	1 PC REAR FENDER LH <i>Regis</i>	892.10 +	
111	1 PC REAR FENDER TRIM LH <i>cracked</i>	355.90 ✓ 258	
112	1 PC REAR FENDER MUDFLAP LH <i>new</i>	76.90 +	
113	1 PC REAR FENDER VENTILATION COVER LH <i>new</i>	65.60 +	
114	1 PC SPARE TYRE PANEL <i>Regis</i>	708.80 +	
115	1 PC SPARE TYRE PANEL RH SPONGE } <i>Del'd</i>	244.10 ✓	
116	1 PC SPARE TYRE PANEL LH SPONGE } <i>Del'd</i>	244.10 ✓	
117	1 PC SPARE TYRE COVER <i>torn</i>	206.90 ✓	
118	1 PC TAIL LAMP LH } <i>cracked</i>	397.10 ✓	
119	1 PC TAIL LAMP - RH } <i>cracked</i>	397.10 ✓	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Estimate No: EST2000166
Date: 19 Aug 2020

Veh Reg No: SMP3356R
Make/Model: TOYOTA VIOS 1.5E
(AUTO)

Chasis No: MR2B23F3201180977
Reg. Date: 23/09/2019
Your Ref No: GBC39A

Claim Type: Third Party
Accident Date: 14/08/2020
TP Veh Reg No: GBC39A

Estimate Repair Cost to Vehicle No :SMP3356R

Quantity	Description	List Price	Amount
		SS	SS
120	1 PC REAR PANEL <i>Distorted</i>	728.70 ✓	
121	1 PC REAR PANEL GARNISH <i>Del</i>	242.30 ✓	
122	1 PC TAIL LAMP PANEL RH <i>Broken</i>	166.70 ✓	
123	1 PC REAR PANEL LOCK SENSORS <i>Called</i>	188.20 ✓	
124	1 PC REAR BUMPER <i>Distorted</i>	482.20 ✓	
125	1 PC REAR BUMPER REINFORCEMENT <i>Best</i>	316.10 ✓	
126	2 PCS REAR BUMPER SIDE RETAINER <i>Nu</i>	287.00 ✓	
127	2 PCS REAR BUMPER RETAINER (SMALL) <i>Nu</i>	145.40 ✓	
128	1 PC REAR BUMPER REFLECTOR - RH <i>Called</i>	92.80 ✓	
129	1 PC REAR BUMPER REFLECTOR - LH <i>Called</i>	92.80 ✓	
130	1 PC EXHAUST PIPE <i>Nu</i>	634.10 <i>45158.4</i> x	
131	2 PCS EXHAUST PIPE MOUNTING <i>Nu</i>	59.60 <i>34318.80</i> x	
		57,694.20	
		Less 25%	14,423.55 43,270.97

Special Net

132	1 PC BONNET NUMBER "644" STICKER <i>Nu</i>	35.00 ✓	
133	1 SET BONNET TRIM CLIPS <i>Nu</i>	60.00 30	
134	1 SET FRT FENDER COWLING CLIPS RH <i>Nu</i>	40.00 +	
135	1 SET FRT FENDER COWLING CLIPS LH <i>Nu</i>	40.00 +	
136	1 SET FRT SUPPORT PANEL TOP TRIM CLIPS <i>Nu</i>	40.00 15	
137	1 SET FRT GRILLE CLIPS <i>Nu</i>	40.00 20	
138	1 SET FRT BUMPER CLIPS <i>Nu</i>	40.00 30	
139	2 PCS "L" PLATE BRACKET <i>Best</i>	70.00 40	
140	1 PC "L" PLATE <i>Best</i>	50.00 ✓	
141	1 PC FRT NUMBER PLATE <i>Best</i>	50.00 ✓	
142	1 SET FRT WIPER PANEL GARNISH CLIPS <i>Nu</i>	40.00 30	
143	1 PC FRT WINDSCREEN SEAL <i>Nu</i>	60.00 40	
144	1 PC FRT WINDSCREEN SEALANT <i>Nu</i>	60.00 80	
145	1 PC FRT WINDSCREEN NUMBER "644" STICKER <i>Nu</i>	35.00 ✓	
146	1 PC ERP BRACKET <i>Nu</i>	40.00 25	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Estimate No: EST2000166
Date: 19 Aug 2020

Veh Reg No: SMP3356R
Make/Model: TOYOTA VIOS 1.5E (AUTO)

Chasis No: MR2B23F3201180977
Reg. Date: 23/09/2019
Your Ref No: GBC39A

Claim Type: Third Party
Accident Date: 14/08/2020
TP Veh Reg No: GBC39A

Estimate Repair Cost to Vehicle No :SMP3356R

Quantity	Description	List Price	Amount
		SS	SS
147	1 PC FRT RH DOOR STICKER <i>?</i>	195.00	160
148	1 PC FRT LH DOOR STICKER <i>?</i>	195.00	160
149	1 PC BOOT LID NUMBER '644' STICKER <i>Nec</i>	35.00	
150	1 SET BOOT LID TRIM CLIPS <i>Nec</i>	40.00	30
151	1 PC REAR NUMBER PLATE <i>Best</i>	50.00	
152	1 SET REAR FENDER TRIM CLIPS RH <i>Nec</i>	60.00	30
153	1 SET REAR FENDER MUDFLAP CLIPS RH <i>Nec</i>	30.00	+
154	1 PC REAR FENDER STICKER RH <i>Nec</i>	190.00	160
155	1 SET REAR FENDER TRIM CLIPS <i>Nec</i>	60.00	30
156	1 SET REAR FENDER MUDFLAP CLIPS <i>Nec</i>	30.00	+
157	1 PC REAR FENDER STICKER <i>Nec</i>	190.00	160
158	1 PC REAR WINDSCREEN SEALANT <i>?</i>	60.00	40
159	1 PC REAR WINDSCREEN SEAL <i>?</i>	60.00	40
160	1 SET REAR PANEL GARNISH CLIPS <i>Nec</i>	40.00	10
161	1 SET REAR BUMPER CLIPS <i>Nec</i>	40.00	30
162	1 SET REAR BUMPER STICKER <i>Nec</i>	195.00	150
163	2 PCS "L" PLATE BRACKET <i>Best</i>	70.00	40
164	1 PC "L" PLATE <i>Best</i>	50.00	
165	1 PC REAR WINDSCREEN INNER SEAL <i>Nec</i>	60.00	+
		2,350.00	2,350.00
	Labour		
166	1 TOWING	60.00	
167	1 TO CHECK WIRING	50.00	30
168	1 TO REMOVE AND REFIT FRONT WINDSCREEN	120.00	
169	1 TO REFILL AIRCON GAS	120.00	
170	1 TO REMOVE AND REFIT DASH BOARD	400.00	220
171	1 TO REMOVE AND REFIT STEERING AIR BAG, DASH BOARD LH AIR BAG, STEERING LOWER AIR BAG, LH & RH SEALT BELT	750.00	500
172	1 TO REMOVE AND REFIT ROOF LH & RH AIR BAG	800.00	350

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Estimate No: EST2000166
Date: 19 Aug 2020

Veh Reg No: SMP3356R
Make/Model: TOYOTA VIOS 1.5E (AUTO)

Chasis No: MR2B23F3201180977
Reg. Date: 23/09/2019
Your Ref No: GBC39A

Claim Type: Third Party
Accident Date: 14/08/2020
TP Veh Reg No: GBC39A

Estimate Repair Cost to Vehicle No :SMP3356R

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
173	1 PC TO REFIX UPHOLSTERY	800.00	300.
174	1 TO SPRAY UNDERSEAL	200.00	80
175	1 (FRONT) TO SPRAY PAINTING	2,000.00	1800
176	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	2,000.00	1200.
177	1 TO PROGRAM AND DIAGNOSE	400.00	280
178	1 TO CHECK WIRING	50.00	30
179	1 TO REPLACE STICKERS	120.00	x
180	1 TO REMOVE AND REFIT SEAT CUSHION	280.00	120.
181	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	150.00	80.
182	1 TO SPRAY UNDERSEAL	180.00	100.
183	1 (REAR) TO SPRAY PAINTING	1,800.00	1400
184	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	2,500.00	1800.
185	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	✓
		12,900.00	12,900.00

8410

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S: CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 14/08/2020
TP Veh Reg No: GBC39A

Estimate No: EST2000166
Date: 19 Aug 2020

Veh Reg No: SMP3356R
Make/Model: TOYOTA VIOS 1.5E
(AUTO)

Chasis No: MR2B23F3201180977
Reg. Date: 23/09/2019
Your Ref No: GBC39A


Estimate Repair Cost to Vehicle No :SMP3356R

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		Total	S\$ 58,520.97
		Add GST @ 7%	4,096.47
		Total Amount Payable	<u>S\$ 62,617.44</u>

TOTAL: SINGAPORE DOLLAR SIXTY TWO THOUSAND SIX HUNDRED SEVENTEEN AND CENTS FORTY FOUR ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Adrian Lj
1/s 20/08/20.

18 Days.

Total: 44373.80

1/s: 325K (Nett Value).