

Estimate

21/08/2020

CHINA TAIPING INSURANCE (S) PTE LTD

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909.

Page # :- 1

Veh # SJZ9799P :-

Veh Model :- BMW 640I GRAN COUPE

Estimate# :- CK420916

	:-
Claim #	

ACC. Date :- 18/08/02

Terms :- C.O.D Days

Attention :- XA017

No.	Description
1	...
2	...
3	...
4	...
5	...
6	...
7	...
8	...
9	...
10	...
11	...
12	...
13	...
14	...
15	...
16	...
17	...
18	...
19	...
20	...
21	...
22	...
23	...
24	...
25	...
26	...
27	...
28	...
29	...
30	...
31	...
32	...
33	...
34	...
35	...
36	...
37	...
38	...
39	...
40	...
41	...
42	...
43	...
44	...
45	...
46	...
47	...
48	...
49	...
50	...
51	...
52	...
53	...
54	...
55	...
56	...
57	...
58	...
59	...
60	...
61	...
62	...
63	...
64	...
65	...
66	...
67	...
68	...
69	...
70	...
71	...
72	...
73	...
74	...
75	...
76	...
77	...
78	...
79	...
80	...
81	...
82	...
83	...
84	...
85	...
86	...
87	...
88	...
89	...
90	...
91	...
92	...
93	...
94	...
95	...
96	...
97	...
98	...
99	...
100	...

U.Price Amounts S\$

Qty

U.Price Amounts S\$

LIST ITEMS :

1. REAR BOOT ~~Cut~~ / X 300 N
2. REAR BOOT LOGO X 300 N
3. REAR BOOT EMBLEM "640I" New -
4. REAR BOOT LAMP LH ? Can -
5. REAR BOOT RUBBER New -
6. REAR LAMP LH X 500
7. REAR BUMPER ~~Cut~~ -
8. REAR BUMPER PDC SENSOR ? Cut /
9. REAR BUMPER NUMBER PLATE LAMP ~~Cut~~ -
10. REAR BUMPER REFLECTOR LH ? Can -
11. REAR BUMPER ADAPTER ? Can -
12. REAR BUMPER WIRE X 800
13. REAR BUMPER SPONGE ? 1 ft
14. REAR BUMPER REINFORCEMENT ? Can -
15. REAR BUMPER LOWER BRACKET
16. REAR BUMPER RIVET New -
17. REAR EXHAUST ? 1 ft
18. REAR EXHAUST TAIL LAMP X pipe (see -)
19. REAR NUMBER PLATE 1 ft
20. REAR PANEL - REPAIR

LIST TOTAL S\$

5% DISCOUNT S\$

LABOUR :

TO CUT & WELD REAR PANEL, TO REPAIR REAR FENDER, REAR END PANEL, TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS

TO SPRAY AFFECTED AREAS

TO REMOVE & REFIX REAR BOOT, REAR LOCK MECHANISM, CHECK & TEST FOR FUNCTION

TO REMOVE & REFIX REAR LUGGAGE, COMPARTMENT
SIDE COVER, SIDE TRIM AND OTHER ATTACHMENT
PARTS

TO RUST PROOF AFFECTED AREAS

LABOUR TOTAL S\$

Remove & refit rear silence - 80

REVIEWS

- | ITEM | QTY | UNIT | PRICE | TOTAL |
|---|-----|------|----------|----------|
| 1. REAR BOOT CUB | 1 | PC | 2,759.55 | 2,759.55 |
| 2. REAR BOOT LOGO X 300 N | 1 | PC | 151.60 | 151.60 |
| 3. REAR BOOT EMBLEM "640I" N | 1 | PC | 164.60 | 164.60 |
| 4. REAR BOOT LAMP LH ? CM | 1 | PC | 417.00 | 417.00 |
| 5. REAR BOOT RUBBER N | 1 | PC | 166.40 | 166.40 |
| 6. REAR LAMP LH X 500 | 1 | PC | 707.00 | 707.00 |
| 7. REAR BUMPER CM | 1 | PC | 2,156.65 | 2,156.65 |
| 8. REAR BUMPER PDC SENSOR ? CM | 1 | PC | 283.25 | 283.25 |
| 9. REAR BUMPER NUMBER PLATE LAMP CM | 1 | PC | 72.45 | 72.45 |
| 10. REAR BUMPER REFLECTOR LH ? CM | 1 | PC | 73.30 | 73.30 |
| 11. REAR BUMPER ADAPTER ? CM | 1 | PC | 198.50 | 198.50 |
| 12. REAR BUMPER WIRE X 500 | 1 | PC | 289.45 | 289.45 |
| 13. REAR BUMPER SPONGE ? 500 | 1 | PC | 167.25 | 167.25 |
| 14. REAR BUMPER REINFORCEMENT ? CM | 1 | PC | 873.65 | 873.65 |
| 15. REAR BUMPER LOWER BRACKET | 2 | PC | 74.25 | 148.50 |
| 16. REAR BUMPER RIVET N | 10 | PC | 5.00 | 50.00 |
| 17. REAR EXHAUST ? 10 | 1 | PC | 1,429.75 | 1,429.75 |
| 18. REAR EXHAUST TAIL LAMP X PIPE (SEE) | 1 | PC | 155.80 | 155.80 |
| 19. REAR NUMBER PLATE BT | 1 | PC | 60.00 | 60.00 |
| 20. REAR PANEL - REPAIR | 1 | PC | 60.00 | 60.00 |

LIST TOTAL S\$

5% DISCOUNT S\$

LABOUR :

TO CUT & WELD REAR PANEL, TO REPAIR REAR FENDER, REAR END PANEL, TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS

TO SPRAY AFFECTED AREAS

TO REMOVE & REFIX REAR BOOT, REAR LOCK MECHANISM, CHECK & TEST FOR FUNCTION

TO REMOVE & REFIX REAR LUGGAGE, COMPARTMENT
SIDE COVER, SIDE TRIM AND OTHER ATTACHMENT
PARTS

TO RUST PROOF AFFECTED AREAS

LABOUR TOTAL S\$

Remove & refit rear silence - 80

Estimate

21/08/2020

CHINA TAIPING INSURANCE (S) PTE LTD

3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1 138827
Veh # :- SJZ9799P
Veh Model :- BMW 640I GRAN COUPE
Estimate# :- CK420916
Claim # :-
ACC. Date :- 18/08/02
Terms :- C.O.D Days
Remarks :-



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1009,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892

Fax: (65) 6270 8314

Cc. Reg. 198904033G

GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

GST @ 7 %

AMOUNT DUE S\$

11,528.46

806.99

12,335.45

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

11,608.46

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5 days

45

24/08/2020

P 1050

Resurvey after

repair