

# HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E  
BEDOK NORTH AVE 4,  
#01-2008/10/12 SINGAPORE 489977  
TEL : 6441 5655 FAX : 6441 5355/6243 8121  
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXXXX624J  
TAN KHENG SOON  
BLK 5 SIMEI STREET  
04-07  
SINGAPORE 529832  
TEL : FAX :  
PH : 84981928  
ATTN :

*Not Authorized  
Lala  
Take the Approval  
3 days.  
21/9/20*

## ESTIMATE BILL

Number : EB00005514  
Date : 20/08/2020  
Case No : AD00011246  
Vehicle No : SKX8326B  
Chassis : ZSU600061332  
Year of Mfr : 2015  
Policy No : 20-MS000231-R01  
Model : TOYOTA HARRIER  
2.0 PREMIUM

Term:

| Sn                                                                                    | DESCRIPTION                              | QTY | U PRICE  | DISC | AMOUNT   |
|---------------------------------------------------------------------------------------|------------------------------------------|-----|----------|------|----------|
| 1                                                                                     | HEADLAMP LH                              | 1.0 | 3,357.30 | 25   | 2,517.98 |
| 2                                                                                     | FRONT FENDER LH                          | 1.0 | 1,446.30 | 25   | 1,084.73 |
| 3                                                                                     | FRONT BUMPER                             | 1.0 | 1,658.90 | 25   | 1,244.18 |
| 4                                                                                     | FRONT BUMPER RETAINER LH                 | 1.0 | 115.20   | 25   | 86.40    |
| List Price - Parts Sub Total                                                          |                                          |     |          |      | 4,933.29 |
| 5                                                                                     | BONNET - REPAIR                          | 1.0 |          |      |          |
| 6                                                                                     | FRONT DOOR LH - REPAIR                   | 1.0 |          |      |          |
| 7                                                                                     | REAR DOOR LH - REPAIR                    | 1.0 |          |      |          |
| Special Nett Price - Parts Sub Total                                                  |                                          |     |          |      | 0.00     |
| Parts Total                                                                           |                                          |     |          |      | 4,933.29 |
| 8                                                                                     | LABOUR TO REMOVE & REFIT NECESSARY PARTS | 1.0 | 700.00   | 0    | 700.00   |
| 9                                                                                     | SPRAY PAINT ON THE AFFECTED AREAS        | 1.0 | 900.00   | 0    | 900.00   |
| 10                                                                                    | ANTI-RUST COATING                        | 1.0 | 150.00   | 0    | 150.00   |
| 11                                                                                    | WIRING                                   | 1.0 | 40.00    | 0    | 40.00    |
| Labour 1 Sub Total                                                                    |                                          |     |          |      | 1,790.00 |
| SINGAPORE DOLLARS : SEVEN THOUSAND ONE HUNDRED NINETY-THREE AND CENTS NINETY-TWO ONLY |                                          |     |          |      | 0.00     |
| Less Excess                                                                           |                                          |     |          |      | 0.00     |
| SUBTOTAL                                                                              |                                          |     |          |      | 6,723.29 |
| GST 7.00%                                                                             |                                          |     |          |      | 470.63   |
| TOTAL                                                                                 |                                          |     |          |      | 7,193.92 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Date of accident : 15/08/2020 11:00 AM. Place : JALAN BUKIT MERAH

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE