

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXXXX624J
TAN KHENG SOON
BLK 5 SIMEI STREET
04-07
SINGAPORE 529832
TEL : FAX :
PH : 84981928
ATTN :

ESTIMATE BILL

Number : EB00005514
Date : 20/08/2020
Case No : AD00011246
Vehicle No : SKX8326B
Chassis : ZSU600061332
Year of Mfr : 2015
Policy No : 20-MS000231-R01
Model : TOYOTA HARRIER
2.0 PREMIUM

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	HEADLAMP LH	1.0	3,357.30	25	2,517.98
2	FRONT FENDER LH	1.0	1,446.30	25	1,084.73
3	FRONT BUMPER	1.0	1,658.90	25	1,244.18
4	FRONT BUMPER RETAINER LH	1.0	115.20	25	86.40
List Price - Parts Sub Total					4,933.29
5	BONNET - REPAIR	1.0			
6	FRONT DOOR LH - REPAIR	1.0			
7	REAR DOOR LH - REPAIR	1.0			
Special Nett Price - Parts Sub Total					0.00
Parts Total					4,933.29
8	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	700.00	0	700.00
9	SPRAY PAINT ON THE AFFECTED AREAS	1.0	900.00	0	900.00
10	ANTI-RUST COATING	1.0	150.00	0	150.00
11	WIRING	1.0	40.00	0	40.00
Labour 1 Sub Total					1,790.00
SINGAPORE DOLLARS : SEVEN THOUSAND ONE HUNDRED NINETY-THREE AND CENTS NINETY-TWO ONLY			Less Excess		0.00
			SUBTOTAL		6,723.29
			GST 7.00%		470.63
			TOTAL		7,193.92

Date of accident : 15/08/2020 11:00 AM. Place : JALAN BUKIT MERAH

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE