

Not Authorized
L/Ry &

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5344P

AAD2008-068

18 AUG 2020

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

SHC 5344P

VF1ABL15AUC279353

RENAULT

LATITUDE

17.8.2020

CHINA TAIPING

30-09-14

	PART	LIST	
1	BUMPER COVER FRT	\$ <i>mgcm</i> 747.20	✓
1	BUMPER SPOILER FRT	\$ <i>sn</i> 344.70	X
1	BUMPER ABSORBER FRT	\$ <i>cm</i> 394.68	✓
1	BUMPER BRACKET FRT LH (Headlamp Lower)	\$ <i>sn</i> 116.47	X
1	BUMPER RETAINER FRT LH	\$ <i>0.1 sn</i> 101.40	✓
1	BUMPER BRACKET FRT RH (Headlamp Lower)	\$ <i>sn</i> 116.47	X
1	BUMPER RETAINER FRT RH	\$ <i>sn</i> 101.40	X
1	BUMPER UNDERTRAY FRT	\$ <i>sn</i> 292.50	X
1	BUMPER GRILLE LOWER FRT	\$ <i>sn</i> 147.00	X
1	BUMPER FOG LAMP GRILLE LH	\$ <i>sn</i> 207.21	X
1	BUMPER FOG LAMP GRILLE RH	\$ <i>sn</i> 207.21	X
1	HEADLAMP LH	\$ <i>mgcm</i> 743.60	✓
1	HEADLAMP RH	\$ <i>sn</i> 743.60	X
1	FENDER PANEL FRT LH	\$ <i>Ry</i> 437.10	✓
1	WHEELARCH FRT LH	\$ <i>Tn</i> 191.40	✓
1	FENDER INSULATOR LH	\$ <i>sn</i> 66.30	X
1	FENDER PANEL FRT RH	\$ <i>R</i> 437.10	X
1	WHEELARCH FRT RH	\$ <i>sn</i> 191.40	X
1	RADIATOR GRILLE	\$ <i>mgcm</i> 969.90	✓
1	RADIATOR GRILLE BADGE 'RENAULT'	\$ <i>ru</i> 225.36	✓
1	RADIATOR GRILLE FRAME	\$ <i>sn</i> 686.00	} X
1	FRAME FULL SUPPORT PANEL	\$ <i>sn</i> 592.70	
1	BONNET	\$ <i>R</i> 1,312.70	
1	AIR CLEANER LOWER	\$ <i>sn</i> 271.26	
1	AIR CLEANER HOSE	\$ <i>sn</i> 175.85	
1	AIR CLEANER BOX	\$ <i>sn</i> 464.20	}
1	DOOR PANEL FRT LH	\$ <i>R</i> 2,844.66	
1	DOOR MIRROR ASSY LH	\$ <i>sn</i> 1,483.40	

Trans-cab Auto Services Pte Ltd

AAD2008-068

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5344P

1	DOOR HINGE UPPER LH	\$	274.50	}	X
1	DOOR HINGE LOWER LH	\$	300.55		
1	DOOR CHECK FRT LH	\$	90.90		
1	DOOR FINISHER FRT LH	\$	258.90		
1	DOOR WAIST SEAL OUTER FRT LH	\$	92.20		
1	DOOR FINISHER CLIP KIT	\$	94.00		
1	DOOR GLASS FRT LH	\$	394.00		
1	DOOR MOULDING BLACK FRT LH	\$	100.50		
1	DOOR REGULATOR FRT LH	\$	501.40		
1	DOOR REGULATOR MOTOR FRT LH	\$	758.10		
1	DOOR PANEL FRT RH	\$	2,844.66		
1	DOOR MIRROR ASSY RH	\$	1,483.40		
1	WIPER RESERVOIR	\$	179.60		
TOTAL		\$	21,985.47		
10%		\$	2,198.55		
		\$	19,786.92		

Special Nett

1	BUMPER CLIP FRT	\$	75.00	}	X
1	BUMPER BRACKET CLIP LH	\$	60.00		
1	BUMPER RETAINER CLIP LH	\$	65.00		
1	BUMPER BRACKET CLIP RH	\$	60.00		
1	BUMPER RETAINER CLIP RH	\$	65.00		
1	BUMPER GRILLE LOWER CLIP	\$	69.00		
1	BUMPER SPOILER CLIP	\$	60.00		
1	BUMPER FOG LAMP GRILLE CLIP	\$	60.00		
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00		
2	FRAME FULL SUPPORT PANEL NUT	\$	55.00		
2	FRAME FULL SUPPORT PANEL STUD	\$	60.00	}	X
1	WHEELARCH CLIP LH	\$	65.00		
1	WHEELARCH CLIP RH	\$	65.00		
1	FRONT LEFT TYRE	\$	300.00		
1	FRONT LEFT TYRE RIM	\$	380.00		
1SET	Front licence plate with holder	\$	100.00		
1SET	RADIATOR GRILLE SCREW	\$	50.00	}	X
1SET	RADIATOR GRILLE FRAME CLIP	\$	55.00		

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6257 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5344P

AAD2008-068

1	FRONT LH DOOR STICKER 'Trans-Cab'	\$	nn	80.00	605N-
1	FRONT LH DOOR STICKER 'Classic'	\$	nn	80.00	155N-
1	FRONT RH DOOR STICKER 'Trans-Cab'	\$	nn	80.00	X
1	FRONT RH DOOR STICKER 'Classic'	\$	nn	80.00	X
1	FRONT LEFT TYRE RIM COVER	\$	nn	65.00	X
1	FRONT RIGHT TYRE RIM COVER	\$	nn	65.00	X
1	FRONT RIGHT TYRE	\$	nn	300.00	X
1	FRONT RIGHT TYRE RIM	\$	nn	380.00	X

TOTAL \$ 2,844.00**TOTAL PARTS \$ 22,630.92****LABOUR**

To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn	350.00	X
To rust-proofing and apply undercoat of the affected areas.	\$		250.00	301
To transfer of door fittings, attachment and perform water seepage test.	\$	nn	350.00	X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		1,600.00	4001
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00	X
Towing Fees.	\$		150.00	501
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5344P

AAD2008-068

Putty and spray painting of the affected portion.	\$	1,600.00	6601
To Check Electrical Lighting Concerned.	\$	170.00	201
TOTAL	\$	5,410.00	
Over All Total	\$	28,040.92	

LUMP SUM (REPAIR DAY)~~20 DAYS~~

3 days

For Official UsePrepared By : _____
(Accident Dept)Verify By : _____
(Accident Workshop)Checked By : _____
(Finance Dept)LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: