



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2104147

INV Date 14/06/2021

Reference CC3/LPC20008753/Kgs3q2

Code LPC2

### PROFESSIONAL SERVICE FEE

Vehicle No. SHD 9624A  
Insured Veh. GBE 742S  
Claim No. 19/20/20/VC000/023546  
Policy No. Z/19/VC00/104472  
Accident Date 14/08/2020  
Inspection Date 19/08/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC3/LPC20008753/Kgs3q2 Date: 14/06/2021 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBE 742S	Veh. Inspected	SHD 9624A	
Policy No.	Z/19/VC00/104472	Coverage (\$)	0.00	
Claim No.	19/20/20/VC000/023546	Excess (\$)	0.00	
Assign From	KENNY	Assign Date	19/08/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTDKB3FU203082598	Colour	M.P. WHITE / RED	
Odometer	86839 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	SAILUN	9 mm	
L/H Front Tyre	195/65 R15	SAILUN	9 mm	
R/H Rear Tyre	195/65 R15	SAILUN	8 mm	
L/H Rear Tyre	195/65 R15	SAILUN	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR DOOR. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	14/08/2020	Inspection Date	19/08/2020	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9624A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	PANEL SUB-ASSY,REAR DOOR,RH	BENT	1,294.90	1,294.90
1	LOCK ASSY,REAR DOOR WITH MOTOR,RH	JAMMED	561.90	561.90
1	HINGE ASSY,REAR DOOR,UPPER RH	TO REPAIR SEE LABOUR	98.90	-
1	HINGE ASSY,REAR DOOR,LOWER RH	TO REPAIR SEE LABOUR	87.10	-
1	CHECK ASSY,REAR DOOR,RH	SERVICEABLE	183.80	-
1	MOULDING ASSY,REAR DOOR BELT,RH	SERVICEABLE	113.50	-
1	HANDLE ASSY,REAR DOOR OUTSIDE,RH	SERVICEABLE	97.40	-
1	FRAME SUB-ASSY,REAR DOOR OUTSIDE HANDLE,RH	SERVICEABLE	193.50	-
1	MOTOR ASSY,POWER WINDOW REGULATOR,REAR RH	BENT	926.00	926.00
1	REGULATOR SUB-ASSY,REAR DOOR WINDOW,RH	JAMMED	206.70	206.70
1	BAR SUB-ASSY,REAR DOOR WINDOW DIVISION,RH	SERVICEABLE	112.30	-
1	MOULDING,REAR DOOR WINDOW FRAME,FRONT RH	SERVICEABLE	56.50	-
1	MOULDING,REAR DOOR WINDOW FRAME,REAR RH	SERVICEABLE	38.60	-
1	MOULDING,REAR DOOR WINDOW FRAME,UPPER RH	SERVICEABLE	92.00	-
1	TAPE,BLACK OUT,NO 1 REAR RH	NECESSARY	21.90	21.90
1	TAPE,BLACK OUT,NO 2 REAR RH	NECESSARY	34.90	34.90
1	TAPE,BLACK OUT,NO 3 REAR RH	NECESSARY	15.40	15.40
1	MOULDING ASSY,BODY ROCKER PANEL,RH	SERVICEABLE	594.80	-
1	PANEL SUB-ASSY,QUARTER,RH	TO REPAIR SEE LABOUR	871.50	-
1	PANEL SUB-ASSY,FRONT DOOR,RH	TO REPAIR SEE LABOUR	1,300.70	-
1	TAPE,BLACK OUT,NO 1 FRT RH	NOT NECESSARY	13.30	-
1	TAPE,BLACK OUT,NO 2 FRT RH	NOT NECESSARY	43.50	-
1	TAPE,BLACK OUT,NO 3 FRT RH	NOT NECESSARY	26.30	-
	LESS 25% DISCOUNT		-1,746.35	-765.42
			5,239.05	2,296.28
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT DOOR STICKER "TRANS-CAB" (SN)	NOT NECESSARY	100.00	-
1	REAR DOOR STICKER "6555-3333" (SN)	NECESSARY	100.00	60.00

Report Ref No. CC3/LPC20008753/Kgs3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET ROCKER PANEL MOULDING CLIP (SN)	NOT NECESSARY	65.00	-
1	TYRE,RIM (SN)	SERVICEABLE	1,879.40	-
			2,144.40	60.00
	<b>LABOUR</b>			
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF HINGE ASSY,REAR DOOR,UPPER RH,HINGE ASSY,REAR DOOR,LOWER RH,PANEL SUB-ASSY,QUARTER,RH AND PANEL SUB-ASSY,FRONT DOOR,RH.		1,500.00	200.00
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.		240.00	30.00
	TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,500.00	220.00
	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
			4,300.00	530.00
<b>GRAND TOTAL</b>			<b>11,683.45</b>	<b>2,886.28</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,886.28</b>

Report Ref No. CC3/LPC20008753/Kgs3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SHD 9624A

### INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SHD 9624A

### RE-INSPECTION

