

Not Notaire
Reservy B4 paint
82886.28

AAD2008-063

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9624A

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

19 AUG 2020

SHD 9624A

JTDKB3FU203082598

TOYOTA

PRIUS

14.8.2020

LONPAC

01/08/2019

PART	LIST
1 PANEL SUB-ASSY, REAR DOOR, RH	\$ 1,294.90 ✓
1 LOCK ASSY, REAR DOOR WITH MOTOR, RH	\$ 561.90 ✓
1 HINGE ASSY, REAR DOOR, UPPER RH	\$ 98.90 ✓
1 HINGE ASSY, REAR DOOR, LOWER RH	\$ 87.10 ✓
1 CHECK ASSY, REAR DOOR, RH	\$ 183.80 ✓
1 MOULDING ASSY, REAR DOOR BELT, RH	\$ 113.50 ✓
1 HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$ 97.40 ✓
1 FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$ 193.50 ✓
1 MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$ 926.00 ✓
1 REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$ 206.70 ✓
1 BAR SUB-ASSY, REAR DOOR WINDOW DIVISION, RH	\$ 112.30 ✓
1 MOULDING, REAR DOOR WINDOW FRAME, FRONT RH	\$ 56.50 ✓
1 MOULDING, REAR DOOR WINDOW FRAME, REAR RH	\$ 38.60 ✓
1 MOULDING, REAR DOOR WINDOW FRAME, UPPER RH	\$ 92.00 ✓
1 TAPE, BLACK OUT, NO.1 REAR RH	\$ 21.90 ✓
1 TAPE, BLACK OUT, NO.2 REAR RH	\$ 34.90 ✓
1 TAPE, BLACK OUT, NO.3 REAR RH	\$ 15.40 ✓
1 MOULDING ASSY, BODY ROCKER PANEL, RH	\$ 594.80 } X
1 PANEL SUB-ASSY, QUARTER, RH	\$ 871.50 }
1 PANEL SUB-ASSY, FRONT DOOR, RH	\$ 1,300.70 }
1 TAPE, BLACK OUT, NO.1 FRT RH	\$ 13.30 }
1 TAPE, BLACK OUT, NO.2 FRT RH	\$ 43.50 }
1 TAPE, BLACK OUT, NO.3 FRT RH	\$ 26.30 }
TOTAL	\$ 6,985.40
25%	\$ 1,746.35
	\$ 5,239.05

Special Nett

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9624A

AAD2008-063

- 1 FRONT DOOR STICKER 'TRANS-CAB'
- 1 REAR DOOR STICKER "6555-3333"
- 1SET ROCKER PANEL MOULDING CLIP
- 1 TYRE, RIM

\$	na	100.00	X
\$	na	100.00	65.00
\$	na	65.00	X
\$	na	1,879.40	X
TOTAL	\$	2,144.40	

TOTAL PARTS \$ **7,383.45**

LABOUR

To Check Electrical Lighting Concerned.

\$ 170.00 201

Panel Beating, Knocking And Straightening The Necessary Portion,
Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,500.00 201

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 240.00 301

To transfer of front door fittings, attachment and perform water seepage test.

\$ na 170.00 601 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 1,500.00 2201

To transfer of rear door fittings, attachment and perform water seepage test.

\$ 170.00 601

To transfer of tyre, rim and on wheel balancing.

\$ na 170.00 X

TOTAL \$ **4,300.00**

Over All Total \$ **11,683.45**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(PART-BY-PART) Repair Days

20 days
2 days