

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9624A*Not Notaire
Presumy B4 paint*

AAD2008-063

82886.28

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

19 AUG 2020**SHD 9624A**

JTDKB3FU203082598

TOYOTA

PRIUS

14.8.2020

LONPAC

01/08/2019

PART		LIST	
1	PANEL SUB-ASSY, REAR DOOR, RH	\$	1,294.90 ✓
1	LOCK ASSY, REAR DOOR WITH MOTOR, RH	\$	561.90 ✓
1	HINGE ASSY, REAR DOOR, UPPER RH	\$	98.90 ✓
1	HINGE ASSY, REAR DOOR, LOWER RH	\$	87.10 ✓
1	CHECK ASSY, REAR DOOR, RH	\$	183.80 ✓
1	MOULDING ASSY, REAR DOOR BELT, RH	\$	113.50 ✓
1	HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$	97.40 ✓
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$	193.50 X
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$	926.00 ✓
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$	206.70 ✓
1	BAR SUB-ASSY, REAR DOOR WINDOW DIVISION, RH	\$	112.30 ✓
1	MOULDING, REAR DOOR WINDOW FRAME, FRONT RH	\$	56.50 ✓
1	MOULDING, REAR DOOR WINDOW FRAME, REAR RH	\$	38.60 ✓
1	MOULDING, REAR DOOR WINDOW FRAME, UPPER RH	\$	92.00 ✓
1	TAPE, BLACK OUT, NO.1 REAR RH	\$	21.90 ✓
1	TAPE, BLACK OUT, NO.2 REAR RH	\$	34.90 ✓
1	TAPE, BLACK OUT, NO.3 REAR RH	\$	15.40 ✓
1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	594.80 } X
1	PANEL SUB-ASSY, QUARTER, RH	\$	871.50 }
1	PANEL SUB-ASSY, FRONT DOOR, RH	\$	1,300.70 }
1	TAPE, BLACK OUT, NO.1 FRT RH	\$	13.30 }
1	TAPE, BLACK OUT, NO.2 FRT RH	\$	43.50 }
1	TAPE, BLACK OUT, NO.3 FRT RH	\$	26.30 }
TOTAL		\$	6,985.40
25%		\$	1,746.35
		\$	5,239.05

Special Nett

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9624A

AAD2008-063

- 1 FRONT DOOR STICKER 'TRANS-CAB'
- 1 REAR DOOR STICKER "6555-3333"
- 1SET ROCKER PANEL MOULDING CLIP
- 1 TYRE, RIM

\$	nn	100.00	X
\$	nn	100.00	60sm
\$	nn	65.00	X
\$	nn	1,879.40	X
TOTAL	\$	2,144.40	

TOTAL PARTS \$ **7,383.45**

LABOUR

To Check Electrical Lighting Concerned.

\$ 170.00 201

Panel Beating, Knocking And Straightening The Necessary Portion,
Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,500.00 2001

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 240.00 301

To transfer of front door fittings, attachment and perform water seepage test.

\$ nn 170.00 60 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ NN 380.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 1,500.00 2201

To transfer of rear door fittings, attachment and perform water seepage test.

\$ 170.00 601

To transfer of tyre, rim and on wheel balancing.

\$ nn 170.00 X

TOTAL \$ **4,300.00**

Over All Total \$ **11,683.45**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(PART-BY-PART) Repair Days

20 days
2 days