



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref :
Our Ref : TP0028/08/20
THIRD PARTY CLAIM
M/S : LAU WAI KIT PATRICK
BLK 298 BEDOK SOUTH AVE 3
#04-13
SINGAPORE 489298

Attn :
Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SLR7329U - HONDA VEZEL
INSURED : ~~CASH~~ Lau Wai Kit
DATE OF ACCIDENT : 18/08/2020
POLICY NO :

LKK Auto Consultants hence notify the Repairer of the following:
Page: 1/2
• To be done before/after spray painting 19/08/2020
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ENGINE# :

CHASSIS# :

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
Replacement of Parts				
1 front headlamp LH <i>CMA</i>	1@	1850.40	1850.40	1,850.40 ✓
2 front headlamp lower bumper retainer <i>CMA</i>	1@	35.00	35.00	35.00 ✓
3 front bumper <i>MS</i>	1@	459.80	459.80	459.80 ✓
4 front bumper side retainer LH <i>Surf</i>	1@	15.70	15.70	15.70 ✓
5 front bumper fog lamp grille <i>2x/2w1</i>	1@	45.00	45.00	45.00 ✓
6 front bumper fog lamp LH <i>CMA</i>	1@	327.40	327.40	327.40 ✓
7 front bumper lower spoiler <i>11</i>	1@	351.00	351.00	351.00 X
8 front bumper reinforcement <i>DD</i>	1@	321.80	321.80	321.80 ✓
9 front grille <i>11</i>	1@	385.00	385.00	385.00 X
10 front grille base outer garnish <i>11</i>	1@	351.80	351.80	351.80 X
11 front fender wheel arch garnish <i>7.11</i>	1@	153.00	153.00	153.00 ✓
				4,295.90
Less 20%				-859.18
Total Material				\$3,436.72
Labour & Misc				

- Remove & install f/grille, f/headlamp, f/bumper, bumper lower spoiler, f/fender wheel arch, knock f/fender, headlamp support panel and restraigthen body & chassos.
- Spray painting.
- Check wiring system.

500 700.00

550 800.00

25.00 ✓

1,525.00

Total Labour

\$1,525.00

Nett Total Before Gst

\$4,961.72

*Not Allowed
hkr
3 days
2900/?
1/5 to the sh. after repair
20/8/20*

*2-3208.1
202
2-2566.48
1-1075.00
3641.48*