



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2103297

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 11/05/2021
Reference CC4/FCI20008763/Upa3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. FBN 8395K
Insured Veh. SHC 3650T
Claim No. D20003274MFSH
Policy No. D-20094922MFSH
Accident Date 17/08/2020
Inspection Date 21/08/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20008763/Upa3q2	
			Date: 11/05/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3650T	Veh. Inspected	FBN 8395K	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20003274MFSH	Excess (\$)	0.00	
Assign From	VIC	Assign Date	20/08/2020	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA MT-03 ABS	c.c	321	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MH3RH125000009327	Colour	BLUE	
Odometer	22417 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/60Z R17	MICHELIN	7 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	160/60Z R17	MICHELIN	7 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/08/2020	Inspection Date	21/08/2020	
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBN 8395K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BEARING CONE	REPEATED	95.00	-
1	FRONT FORK ASSY	BENT / TWISTED	880.00	880.00
1	FORK UNDER BRACKET	BENT	450.00	325.00
1	METER ASSY	CUT	780.00	780.00
1	WIND SCREEN	CRACKED	60.00	60.00
1	PILOT LOGHT	NOT NECESSARY	150.00	-
1	HEAD LAMP	CUT	200.00	200.00
1	FRONT SIGNAL O/S	CUT	120.00	90.00
1	HEAD LAMP COVER FRONT (MATT BLACK)	SERVICEABLE	35.00	-
1	FRONT FENDER	TO REPAIR SEE LABOUR	80.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	225.00	-
1	FRONT RIM	SERVICEABLE	550.00	-
1	BRAKE LEVER	SCRATCHED	30.00	30.00
1	SET MIRROR	CUT	130.00	130.00
1	HANDLE -BAR	BENT	75.00	75.00
1	SET BALANCER	SCRATCHED	30.00	30.00
1	BRAKE PUMP ASSY TOP	CUT	140.00	140.00
1	BRAKE PEDAL	CUT	65.00	65.00
1	SET RIDER FOOTREST	BENT	100.00	100.00
1	SET RIDER FOOTREST BRACKET	NOT NECESSARY	160.00	-
1	SET PILLAR FOOTREST	CUT	60.00	60.00
1	SET PILLAR FOOTREST BRACKET	NOT NECESSARY	130.00	-
1	REAR SIDE COVER (BLACK)-R/H	NOT NECESSARY	45.00	-
1	ENGINE BUSH	CUT	110.00	110.00
1	ENGINE BAR	CUT	220.00	220.00
	LESS 10% DISCOUNT		-492.00	-329.50
			4,428.00	2,965.50
	<u>SPECIAL NETT ITEMS</u>			
2	FORK OILS (SN)	NECESSARY (1 PCS ONLY)	30.00	15.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FORK OIL SEALS (SN)	NECESSARY (1 PCS ONLY)	56.00	28.00
1	SET STEERING CONE (SN)	NECESSARY	120.00	80.00
1	REAR BOX (SN)	CUT	280.00	250.00
1	EXHAUST PIPE ASSY (SN)	DENTED	550.00	480.00
			1,036.00	853.00
	LABOUR			
	TO PROVIDE TOWING SERVICE.		50.00	30.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR.INCLUSIVE OF THE REPAIR OF FRONT FENDER .		380.00	250.00
			510.00	280.00
GRAND TOTAL			5,974.00	4,098.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,200.00

Report Ref No. CC4/FCI20008763/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBN 8395K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBN 8395K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBN 8395K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

