

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

First

Owner : Koh Wing Hong

Accident Date : 17-Aug-20

Vehicle No : FBN8395K

Vehicle Model : Yamaha MT-03
ABS

Estimated Repair Costs

Qty	Description List Items		Amount S(\$)
1	Bearing cone	Not Auth'd	Repair \$ 95.00 X
1	Front fork assy	21/8/20	Auth'd \$ 880.00 2
1	Fork under bracket 325	2/5 \$ 3200	Seat \$ 450.00 2
1	Meter assy	4 days	Cut \$ 780.00 ✓
1	Wind screen	4 days	Cut \$ 60.00 ✓
1	Pilot loght	4 days	17 \$ 150.00 X
1	Head lamp	4 days	Cut \$ 200.00 ✓
1	Front signal (1 set) 1/5 90	4 days	Cut \$ 120.00 ✓
1	Head lamp cover front (matt black)	4 days	Svc \$ 35.00 X
1	Front fender	4 days	12 \$ 80.00 X
1	Front brake disc	4 days	11 \$ 225.00 X
1	Front rim	4 days	Svc \$ 550.00 X
1	Brake lever	4 days	Svc \$ 30.00 ✓
1	Mirror (1 set)	4 days	Cut \$ 130.00 ✓
1	Handle-bar	4 days	Seat \$ 75.00 2
1	Balancer (1 set)	4 days	Svc \$ 30.00 ✓
1	Brake pump assy top	4 days	Cut \$ 140.00 ✓
1	Brake pedal	4 days	Cut \$ 65.00 ✓
1	Rider footrest (1 set)	4 days	Seat \$ 100.00 ✓
1	Rider footrest bracket (1 set)	4 days	11 \$ 160.00 X
1	Pillion footrest (1 set)	4 days	Cut \$ 60.00 ✓
1	Pillion footrest bracket (1 set)	4 days	11 \$ 130.00 X
1	Rear side cover (black) - R/H	4 days	11 \$ 45.00 X
1	Engine bush	4 days	Cut \$ 110.00 ✓
1	Engine bar	4 days	Cut \$ 220.00 ✓
			\$ 4,920.00
Less 10%			\$ 492.00
			\$ 4,428.00

3295
100
2965.50

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Owner : Koh Wing Hong

Accident Date : 17-Aug-20

Vehicle No : FBN8395K

Vehicle Model : Yamaha MT-03
ABS

Estimated Repair Costs

<u>Special Net Items</u>				
2	Fork oils	15	Net \$	30.00 15
2	Fork oil seals	28	Net \$	56.00 pc
1	Steering cone (1 set)	80	Net \$	120.00 ✓
1	Rear box		Net \$	280.00 250
1	Exhaust pipe assy	450	Net \$	550.00 ✓
			\$	1,036.00

<u>S/No.</u>	<u>Labour</u>			
1	To provide towing service		\$	50.00 30
2	To check wiring and reset headlamp focusing		Net \$	80.00 X
3	To provide labour		250 \$	380.00
			\$	510.00

Grand Total

\$ 5,974.00

Singapore Dollars: Five Thousand Nine Hundred and Seventy-Four only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2865.50
S.N-283.00
L-280
6098.5

1 Kaki Bukit Ave 6 #02-62 Singapore 417883
Tel : (65) 6752 7740 Fax : (65) 6752 8669
Email : erofia2@gmail.com
Co. Reg. No : 53059123E

Date: 18/8/20

EROFIA MOTOR WORKSHOP

Authorised Signature