



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



### ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
NUR'ASHIKIN BINTE BAHAROM	Cust No/Name LCV09897/NUR'ASHIKIN BINTE BAHAROM
BLK 701 CHOA CHU KANG STREET 53	Reg No/Reg Date SML5075J / 24/05/201
#10-24	Date In/Mileage / 0
SINGAPORE 680701	Chassis No KNAF5416MK5026596
Contact No Mobile: 81278284	Engine No G4FGJH722463
	Make/Model KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	18/08/2020/ 17:51	QUD	247 / DonBong	19644

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON MOULDING ASSY-SIDE SILL,RH FILM-ANTI CHIPPG RH, REPAIR REAR BUMPER FACE, REPAIR RH REAR DOOR, REPAIR RH FRONT DOOR, REPAIR RH FRONT FENDER				1100 <del>1650.00</del>
E PNT88000 REMOVE AND INSTALL PARKING ASSIST				80 <del>100.00</del>
E PNT98000 PAINT WORK SPRAY REAR BUMPER FACE, RH REAR FENDER, RH REAR DOOR, RH FRONT DOOR, MOULDING ASSY-SIDE SILL,RH RH FRONT FENDER AND AFFECTED PORTION				2310 <del>2940.00</del>
M SUNDRY SUPPLY RH FRONT SPORT RIM				? 838.00
M SUNDRY LABOUR RENEW RH FRONT SPORT RIM INCLUDING BALANCING				? 40.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment				? 120.00
A 20000001 RENEW FRONT UNDERCARRIAGE DAMAGES				? <del>550.00</del>
M SUNDRY APPLY BODY COATING PROTECTION (Invoile)				? 550.00
M SUNDRY SUNDRIES				20 <del>50.00</del>
M BRACKET ASSY-RR BPR SIDE UPR,L	1.00	25.00	00.00	25.00
M BRACKET-ASSY RR BPR SIDE UPR,R	1.00	31.00	00.00	31.00
M FILM-ANTI CHIPPG RH	1.00	27.00	00.00	27.00
M MOULDING ASSY-SIDE SILL,RH repair	1.00	279.00	00.00	279.00
M HUB ASSY-FR WHEEL X	1.00	436.00	00.00	436.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

SURVEYOR NAME: RASHID - 4p 900/100/58SURVEYOR SIGNATURE: [Signature]DATE: 26/08/2020 @ 1030REMARKS: 7 days

Confirm &amp; accepted by

Rashid after repair

7% GST on **Nett** 7,636.00 534.52

Total Payable 8,170.52

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.