



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2104205

INV Date 14/06/2021

Reference CC4/LPC20008767/Kba3q2

Code LPC2

### PROFESSIONAL SERVICE FEE

Vehicle No. SKX 5368A  
Insured Veh. YM 3267M  
Claim No. 20/20/20/VC00/023541  
Policy No. Z/20/VC00/107149  
Accident Date 14/08/2020  
Inspection Date 14/09/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC20008767/Kba3q2	Date: 14/06/2021
			Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YM 3267M	Veh. Inspected	SKX 5368A	
Policy No.	Z/20/VC00/107149	Coverage (\$)	0.00	
Claim No.	20/20/20/VC00/023541	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	20/08/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA CAMRY (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	MR053DK5100104866	Colour	METALLIC GREY	
Odometer	110861 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	MICHELIN	8 mm	
L/H Front Tyre	215/60 R16	MICHELIN	8 mm	
R/H Rear Tyre	215/60 R16	MICHELIN	6 mm	
L/H Rear Tyre	215/60 R16	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	14/08/2020	Inspection Date	14/09/2020	
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>2 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 5368A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	BENT	518.70	518.70
1	FRONT BUMPER CENTRE LOWER GRILLE WITH CHROME SURROUND RIM	CRACKED	750.00	750.00
1	FRONT RADIATOR CHROME MOULDING	NECESSARY	102.80	102.80
	LESS 25% DISCOUNT		-342.88	-342.87
			1,028.62	1,028.63
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT NUMBER PLATE (SN)	DENTED	40.00	40.00
			40.00	40.00
	<b><u>LABOUR</u></b>			
	TO REMOVE +RENEW ABOVE PARTS.		200.00	200.00
	TO SPRAY PAINT .		300.00	250.00
			500.00	450.00
	<b>GRAND TOTAL</b>		<b>1,568.62</b>	<b>1,518.63</b>

<b>RECOMMENDED COST OF REPAIRS</b>			<b>1,518.63</b>
------------------------------------	--	--	-----------------

Report Ref No. CC4/LPC20008767/Kba3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SKX 5368A**

**INSPECTION**







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SKX 5368A

### RE-INSPECTION

