

來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No : EST0025454
Lim Say Yan

Page : 1 of 1
Your ref : TP-YM 3267M Lonpac
Job No : 71541
Our ref : 20.08.13
Payment :
Date : 20/8/2020

Attn : *NOT WITHIN*

Vehicle No : SKX 5368A
Vehicle Model : Toyota Camry
Accident on : 14/8/2020

*Rekey B4 paint \$1,518.63
2 days*

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
		Supply of Parts:			
1.00	Pc	Front bumper	518.70	25.00	<i>B1</i> 389.03 ✓
1.00	Pc	Front bumper centre lower grille with chrome surround rim	750.00	25.00	<i>CM</i> 562.50 ✓
		Special nett item:			
1.00	Pc	Front number plate	40.00		<i>Nd</i> 40.00 ✓
		Labour & Misc:			
1.00		To remove + renew above parts	200.00		200.00 ✓
1.00		To spray paint	300.00		<i>25%</i> 300.00 ✓

Supplementary Item

1. Front radiator chrome moulding 102.80 25.00 77.10

✓ NEC

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Sub-Total
GST 7.00%
Total

Acknowledged by Repairer
Signature:
Date:

1,491.53
104.41
1,595.94

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."