

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Aug 2020 Edit Reg		20 Aug 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by adjuster]						
Insured: JUHARI BIN MOKIN , ID: S1161793Z									
Main Claimant: TAN TAI PHONG , ID: S0021744A									
Vehicle Reg. No.: FBJ181J		Date of Loss: 17/08/2020 00:00 - :59 [80 Months and 7 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 7768584000SG		Policy/Cover Note No.: 0100646504 (TP, Fire & Theft)							
Vehicle Reg. No. (Insured): SGH6916T		Policy No. (Claimant):							
		Excess:							
Repairer: Equator Brotherhood (HQ) 25 kaki bukit rd 4 #03-79 synergy @ kb, 417800 Kaki Bukit - Tel: 63846939 / 90113391									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 01/09/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
AIG_SG (24/08/2020): Request to upload TP GIA Report									
ALL ASSOCIATED TASKS ☐			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBJ181J (7768584000SG)**
[SGH6916T]

TP

TAN TAI PHONG
Aug 17 2020 12:00AM
[JUHARI BIN MOKIN]
Equator Brotherhood

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/08/20 18:19	General View	 Load JPG	
2	21/08/20 18:19	General View	 Load JPG	
3	21/08/20 18:19	General View	 Load JPG	
4	21/08/20 18:19	General View	 Load JPG	
5	21/08/20 18:19	General View	 Load JPG	
6	21/08/20 18:19	General View	 Load JPG	
7	21/08/20 18:19	General View	 Load JPG	
8	21/08/20 18:19	General View	 Load JPG	
9	21/08/20 18:19	General View	 Load JPG	
10	21/08/20 18:19	General View	 Load JPG	
11	21/08/20 18:19	General View	 Load JPG	
12	21/08/20 18:19	General View	 Load JPG	
13	21/08/20 18:19	General View	 Load JPG	
14	21/08/20 18:19	General View	 Load JPG	
15	21/08/20 18:19	General View	 Load JPG	
16	21/08/20 18:19	General View	 Load JPG	
17	21/08/20 18:19	General View	 Load JPG	
18	21/08/20 18:19	General View	 Load JPG	
19	21/08/20 18:19	General View	 Load JPG	
20	21/08/20 18:19	General View	 Load JPG	
21	21/08/20 18:19	General View	 Load JPG	
22	21/08/20 18:19	General View	 Load JPG	
23	21/08/20 18:19	General View	 Load JPG	
24	21/08/20 18:19	General View	 Load JPG	
25	21/08/20 18:19	General View	 Load JPG	
26	21/08/20 18:19	General View	 Load JPG	
27	21/08/20 18:19	General View	 Load JPG	
28	21/08/20 18:19	General View	 Load JPG	
29	21/08/20 18:19	General View	 Load JPG	
30	21/08/20 18:19	General View	 Load JPG	
31	21/08/20 18:19	General View	 Load JPG	
32	21/08/20 18:19	General View	 Load JPG	
33	21/08/20 18:19	General View	 Load JPG	
34	21/08/20 18:19	General View	 Load JPG	
35	21/08/20 18:19	General View	 Load JPG	
36	21/08/20 18:19	General View	 Load JPG	
37	21/08/20 18:19	General View	 Load JPG	
38	21/08/20 18:19	General View	 Load JPG	
39	21/08/20 18:19	General View	 Load JPG	
40	21/08/20 18:19	General View	 Load JPG	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
41	21/08/20 18:19	General View		Load JPG	
42	21/08/20 18:19	General View		Load JPG	
43	21/08/20 18:19	General View		Load JPG	
44	21/08/20 18:19	General View		Load JPG	
45	21/08/20 18:19	General View		Load JPG	
46	21/08/20 18:19	General View		Load JPG	
47	21/08/20 18:19	General View		Load JPG	
48	21/08/20 18:19	General View		Load JPG	
49	21/08/20 18:19	General View		Load JPG	
50	21/08/20 18:19	General View		Load JPG	
51	21/08/20 18:19	General View		Load JPG	
52	21/08/20 18:19	General View		Load JPG	
53	21/08/20 18:19	General View		Load JPG	
54	21/08/20 18:19	General View		Load JPG	
55	21/08/20 18:19	General View		Load JPG	
56	21/08/20 18:19	General View		Load JPG	
57	21/08/20 18:19	General View		Load JPG	
58	21/08/20 18:19	General View		Load JPG	
59	21/08/20 18:19	General View		Load JPG	
60	21/08/20 18:19	General View		Load JPG	
61	21/08/20 18:19	General View		Load JPG	
62	21/08/20 18:19	General View		Load JPG	
63	21/08/20 18:19	General View		Load JPG	
64	21/08/20 18:19	Chassis Number		Load JPG	

Documentation

1 per page

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	24/08/20 17:51	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG20008776/ETF3S2**Date:** 31/08/2020**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0100646504
Claimant Vehicle No :	FBJ181J	Insured Vehicle No :	SGH6916T
Date of Loss:	17/08/2020	Nature of Claim:	TP
		Claim No:	7768584000SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBJ181J	Engine No:	50C663428
Make & Model:	YAMAHA JUPITER MX, 134cc HC	Chassis No:	MH350C004DK663273
Reg. Date:	10/12/2013 (Man. Year: 2013)	Odometer:	15160 km
Colour:	Purple		
Engine Capacity:	134 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	60/70-17	Rear Tyre Size:	60/70-17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	20/08/2020	
Date Inspected:	21/08/2020	Inspected At: Equator Brotherhood (HQ) 25 kaki bukit rd 4 #03-79 synergy @ kb Singapore 417800
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Cut	0.00 F	*- F
2	1		*FRONT RIM	Cut	0.00 F	*- F
3	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
4	1		*FRONT FORK ASSY	Bent	0.00 F	*- F
5	1		*FRONT HEADLAMP	Cut	0.00 F	*- F
6	1		*ERP UNIT	Cut	0.00 F	*- F
7	1		*STEERING CONE	Necessary	0.00 F	*- F
8	1		*HANDLE BAR	Bent	0.00 F	*- F
9	1		*HANDLE BAR COVER	Cut	0.00 F	*- F
10	1		*HANDLE BAR BALANCER RH	Cut	0.00 F	*- F
11	1		*HAND BRAKE LEVER	Cut	0.00 F	*- F
12	2		*FAIRING SHIELD (RH/LH FRONT)	Cut	0.00 F	*- F
13	1		*FRONT FAIRING	Cut	0.00 F	*- F
14	1		*FRONT FOOT REST	Cut	0.00 F	*- F
15	1		*FRONT FOOT REST BRACKET	Bent	0.00 F	*- F
16	1		*REAR FOOT REST	Cut	0.00 F	*- F
17	1		*EXHAUST MUFFLER HEAT SHIELD	Cut	0.00 F	*- F
18	1		*EXHAUST MUFFLER ASSY	Cut	0.00 F	*- F
19	1		*REAR BOX	Cut	0.00 F	*- F
20	1		*EMBLEM	Necessary	0.00 F	*- F
21	1		*STICKER	Necessary	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >