

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT120008780/Uqf3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBN1596T

at Workshop m/s BHH

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$ 9500

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lump Sum: 131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

L7A5546

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBN1596T Yr Regn: 7,18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha NMAX 155 c.c 155

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 33671 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MH3SG431000007369

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110-70-13

R: 130-70-13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. mm L/Bal. mm

D.O.A. 10/8/20 D.O.I. 21/8/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S, 1/5 Body.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

NFT 3984

23/8/20 P/P \$1670.40 confirmed w/h Raymond CRD B1804.60, 5227

23/09/20 @ 11.41am revised to Jenny Low via Messenger.

Date/Time, File Pass to?

☐

Preli. Report

1) 23/9 11.41am

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Report Format: MER-7P

Lump Sum T.I.B.I.: (\$ 1670.40)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) S + RS, SI

) Photos

) Others

TOTAL



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

Customer :

CHINA TAIPING INSURANCE (S) PTE LTD
105 CECIL STREET
#18-00 / 19-00
THE OCTAGON
S'PORE 069534

ATTN: CHINA TAIPING INSURANCE (S) PTE LTD

VEHICLE NO. : FBN1596T
MAKE/MODEL : YAM / NMAX155 ABS

QUOTATION

LKK Auto Consultants hence notify
the P: **36561** the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
DATE of party survey: **12/08/2020** "out Prejudice" basis
CLAIM NO. mod: **11594** is allowed
POLICY NO. **MC/00833695** surveyed and
is subject to final approval from Insurance Company

FROM: **HASRIANAH**

Signature:

Date:

(Page 1 of 4)

S/N	Description	Action	Qty	Unit Price	Amount
1	BAR HANDLE P/N: 58072	REPLACE	1.00	\$33.00	33.00 X
2	BELLY PAN P/N: 58094	REPLACE	1.00	\$34.00	34.00
3	BOARD FOOTREST LH P/N: 59588	REPLACE	1.00	\$52.00	52.00
4	BOARD FOOTREST RH P/N: 59589	REPLACE	1.00	\$52.00	52.00
5	BOX FILTER AIR OUTER P/N: 58141	REPLACE	1.00	\$18.00	18.00
6	BOX FILTER AIR OUTER FRONT P/N: 58164	REPLACE	1.00	\$11.00	11.00
7	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220	REPLACE	1.00	\$222.00	222.00 200
8	COVER CLUTCH OUTER P/N: 58147	REPLACE	1.00	\$28.00	28.00
9	COVER CLUTCH OUTER DAMPER 1 P/N: 58111	REPLACE	1.00	\$12.00	12.00
10	COVER CLUTCH OUTER DAMPER 2 P/N: 58172	REPLACE	1.00	\$7.00	7.00
11	COVER CLUTCH OUTER DAMPER 3 P/N: 58107	REPLACE	1.00	\$7.00	7.00
12	COVER CLUTCH OUTER DAMPER 4 P/N: 58140	REPLACE	1.00	\$12.00	12.00
13	COVER SIDE CENTRE LH (WHITE) P/N: 58097	REPLACE	1.00	\$30.00	30.00

*36561 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0383
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
14	COVER SIDE CENTRE RH (WHITE) P/N: 58117	REPLACE	1.00	\$30.00	30.00
15	COVER UPPER HANDLE P/N: 60919	REPLACE	1.00	\$17.00	17.00
16	EMBLEM P/N: 56570	REPLACE	1.00	\$10.00	10.00
17	EMBLEM (YAMAHA) LOGO P/N: 57069	REPLACE	2.00	\$11.00	22.00
18	FOOTREST REAR ASSY 1 LH P/N: 58212	REPLACE	1.00	\$33.00	33.00 X
19	FOOTREST REAR ASSY 1 RH P/N: 58213	REPLACE	1.00	\$33.00	33.00 X
20	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	16.00	\$63.00	1,008.00
21	LAMP SIGNAL FRONT RH P/N: 59592	REPLACE	1.00	\$35.00	35.00
22	LEVER BRAKE LH P/N: 58145	REPLACE	1.00	\$18.00	18.00
23	LEVER BRAKE RH P/N: 58185	REPLACE	1.00	\$18.00	18.00 X
24	MIRROR LH P/N: 58099	REPLACE	1.00	\$37.00	37.00
25	MIRROR RH P/N: 58187	REPLACE	1.00	\$37.00	37.00 X
26	MUDGUARD FRONT (WHITE) P/N: 58087	REPLACE	1.00	\$52.00	52.00
27	PROTECTOR EXHAUST P/N: 58086	REPLACE	1.00	\$38.00	38.00
28	RIVET P/N: 56583	REPLACE	10.00	\$2.00	20.00
29	RIVET P/N: 56583	REPLACE	2.00	\$2.00	4.00
30	SIDE STAND P/N: 58211	REPLACE	1.00	\$24.00	24.00 X
31	SPRAY LACQUER ON CENTER COVER LH	Spray	1.00	\$91.00	91.00 60
32	SPRAY LACQUER ON CENTER COVER RH	Spray	1.00	\$91.00	91.00 60
33	SPRAY LACQUER ON FRONT COWLING LH	Spray	1.00	\$91.00	91.00 60
34	SPRAY LACQUER ON FRONT COWLING RH	Spray	1.00	\$91.00	91.00 60
35	SPRAY LACQUER ON FRONT MUDGUARD	Spray	1.00	\$49.00	49.00 30

*36561 *

bizSAFE₃

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0383
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
36	SPRAY LACQUER ON FRONT PROTECTOR LH	Spray	1.00	\$63.00	50 63.00 50
37	SPRAY LACQUER ON FRONT PROTECTOR RH	Spray	1.00	\$63.00	50 63.00 50
38	SPRAY LACQUER ON TAIL COVER LEFT	Spray	1.00	\$63.00	50 63.00 50
39	SPRAY PAINT ON CENTER COVER LH	Spray	1.00	\$91.00	11 91.00 X
40	SPRAY PAINT ON CENTER COVER RH	Spray	1.00	\$91.00	11 91.00 X
41	SPRAY PAINT ON FRONT COWLING LH	Spray	1.00	\$91.00	11 91.00 X
42	SPRAY PAINT ON FRONT COWLING RH	Spray	1.00	\$91.00	11 91.00 X
43	SPRAY PAINT ON FRONT PROTECTOR LH	Spray	1.00	\$63.00	11 63.00 X
44	SPRAY PAINT ON FRONT PROTECTOR RH	Spray	1.00	\$63.00	11 63.00 X
45	SPRAY PAINT ON TAIL COVER LEFT	Spray	1.00	\$63.00	11 63.00 X
46	STAND MAIN P/N: 58138	REPLACE	1.00	\$66.00	11 66.00 X
47	STICKER (CERTIS CISCO) LOGO NEW MODEL LH/RH P/N: 61181	REPLACE	1.00	\$44.00	11 44.00 S.N
48	STICKER (CISCO) COVER CENTRE LH P/N: 58614	REPLACE	1.00	\$37.00	11 37.00 S.N
49	STICKER (CISCO) COVER CENTRE RH P/N: 58615	REPLACE	1.00	\$37.00	11 37.00 S.N
50	STICKER (CISCO) COWLING FRONT LH P/N: 58616	REPLACE	1.00	\$37.00	11 37.00 S.N
51	STICKER (CISCO) COWLING FRONT RH P/N: 58617	REPLACE	1.00	\$37.00	11 37.00 S.N
52	STICKER (CISCO) LINING COVER REAR LH P/N: 61573	REPLACE	1.00	\$15.00	11 15.00 S.N
53	STICKER (CISCO) MUDGUARD FRONT P/N: 58618	REPLACE	1.00	\$37.00	11 37.00 S.N
54	TRANSPORT CHARGES P/N: 07169		1.00	\$56.00	56.00 35-

SUB TOTAL

\$3,475.00

GST @ 7 %

\$243.25

GRAND TOTAL (SGD)

\$3,718.25

50% deposit required before ordering of parts.

Validity: 30 days

*36561 *

bizSAFE₃

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
------------	--------------------	---------------	------------	-------------------	---------------

For & on Behalf of

Acknowledge & Accepted By

BAN HOCK HIN CO PTE LTD



HASRIANAH

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*36561 *

bizSAFE₃

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO : 2002-1-0383
ISO 9001 : 2015



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES / SERVICE CENTRE
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

QUOTATION

Customer :

NO. : 36561

- Rev. 1

CHINA TAIPING INSURANCE (S) PTE LTD
105 CECIL STREET
#18-00 / 19-00
THE OCTAGON
S'PORE 069534
ATTN: MOTOR CLAIMS DEPT

DATE : 12/08/2020
CLAIM NO. : 11594
POLICY NO. : MC/00833695

FROM : HASRIANAH

VEHICLE NO. : FBN1596T
MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BELLY PAN P/N: 58094	REPLACE	1.00	\$34.00 Disc %: 10.00	30.60
2	BOARD FOOTREST LH P/N: 59588	REPLACE	1.00	\$52.00 Disc %: 10.00	46.80
3	BOARD FOOTREST RH P/N: 59589	REPLACE	1.00	\$52.00 Disc %: 10.00	46.80
4	BOX FILTER AIR OUTER P/N: 58141	REPLACE	1.00	\$18.00 Disc %: 10.00	16.20
5	BOX FILTER AIR OUTER FRONT P/N: 58164	REPLACE	1.00	\$11.00 Disc %: 10.00	9.90
6	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220	REPLACE	1.00	\$200.00 Disc %: 10.00	180.00
7	COVER CLUTCH OUTER P/N: 58147	REPLACE	1.00	\$28.00 Disc %: 10.00	25.20
8	COVER CLUTCH OUTER DAMPER 1 P/N: 58111	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
9	COVER CLUTCH OUTER DAMPER 2 P/N: 58172	REPLACE	1.00	\$7.00 Disc %: 10.00	6.30
10	COVER CLUTCH OUTER DAMPER 3 P/N: 58107	REPLACE	1.00	\$7.00 Disc %: 10.00	6.30
11	COVER CLUTCH OUTER DAMPER 4 P/N: 58140	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
12	COVER SIDE CENTRE LH (WHITE) P/N: 58097	REPLACE	1.00	\$30.00 Disc %: 10.00	27.00
13	COVER SIDE CENTRE RH (WHITE) P/N: 58117	REPLACE	1.00	\$30.00 Disc %: 10.00	27.00

*36561 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0363
ISO 9001:2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
14	COVER UPPER HANDLE P/N: 60919	REPLACE	1.00	\$17.00 Disc %: 10.00	15.30
15	EMBLEM P/N: 56570	REPLACE	1.00	\$10.00 Disc %: 10.00	9.00
16	EMBLEM (YAMAHA) LOGO P/N: 57069	REPLACE	2.00	\$11.00 Disc %: 10.00	19.80
17	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	1.00	\$300.00	300.00
18	LAMP SIGNAL FRONT RH P/N: 59592	REPLACE	1.00	\$35.00 Disc %: 10.00	31.50
19	LEVER BRAKE LH P/N: 58145	REPLACE	1.00	\$18.00 Disc %: 10.00	16.20
20	MIRROR LH P/N: 58099	REPLACE	1.00	\$37.00 Disc %: 10.00	33.30
21	MUDGUARD FRONT (WHITE) P/N: 58087	REPLACE	1.00	\$52.00 Disc %: 10.00	46.80
22	PROTECTOR EXHAUST P/N: 58086	REPLACE	1.00	\$38.00 Disc %: 10.00	34.20
23	RIVET P/N: 56583	REPLACE	10.00	\$2.00 Disc %: 10.00	18.00
24	RIVET P/N: 56583	REPLACE	2.00	\$2.00 Disc %: 10.00	3.60
25	SPRAY LACQUER ON CENTER COVER LH	Spray	1.00	\$60.00	60.00
26	SPRAY LACQUER ON CENTER COVER RH	Spray	1.00	\$60.00	60.00
27	SPRAY LACQUER ON FRONT COWLING LH	Spray	1.00	\$60.00	60.00
28	SPRAY LACQUER ON FRONT COWLING RH	Spray	1.00	\$60.00	60.00
29	SPRAY LACQUER ON FRONT MUDGUARD	Spray	1.00	\$30.00	30.00
30	SPRAY LACQUER ON FRONT PROTECTOR LH	Spray	1.00	\$50.00	50.00
31	SPRAY LACQUER ON FRONT PROTECTOR RH	Spray	1.00	\$50.00	50.00
32	SPRAY LACQUER ON TAIL COVER LEFT	Spray	1.00	\$50.00	50.00
33	STICKER (CERTIS CISCO) LOGO NEW MODEL LH/RH P/N: 61181	REPLACE	1.00	\$44.00	44.00
34	STICKER (CISCO) COVER CENTRE LH P/N: 58614	REPLACE	1.00	\$37.00	37.00
35	STICKER (CISCO) COVER CENTRE RH P/N: 58615	REPLACE	1.00	\$37.00	37.00

*36561 *

bizSAFE₃

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
36	STICKER (CISCO) COWLING FRONT LH P/N: 58616	REPLACE	1.00	\$37.00	37.00
37	STICKER (CISCO) COWLING FRONT RH P/N: 58617	REPLACE	1.00	\$37.00	37.00
38	STICKER (CISCO) LINING COVER REAR LH P/N: 61573	REPLACE	1.00	\$15.00	15.00
39	STICKER (CISCO) MUDGUARD FRONT P/N: 58618	REPLACE	1.00	\$37.00	37.00
40	TRANSPORT CHARGES P/N: 07169		1.00	\$35.00	35.00

SUB TOTAL

\$1,670.40

GST @ 7 %

\$116.93

GRAND TOTAL (SGD)

\$1,787.33**50% deposit required before ordering of parts.**

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By

**RAYMOND**

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

36561 *bizSAFE₃*