

Not Notion
 61 Bay @ 5450h
 Resurvey After Paint
 Today



ESTIMATE TO REPAIR

VEHICLE NO. : GZ 9797 E
 MAKE : OPEL
 MODEL : COMBOL2H1 1.6 CDTI AT 6DR
 YEAR : 2016
 CHASSIS NO : WOL6WYL11H9597446

SURVEYOR NAME : Ukk 24 AUG 2020
 DATE OF SURVEY :
 TIME OF SURVEY :

DATE : 20-Aug-20
 DATE OF ACCIDENT : 18-Aug-20
 THIRD PARTY REF : EA 292 J
 THIRD PARTY REF : ERGO INSURANCE PTE. LTD.

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper →			At/cm \$ 800.00	✓
1 pc	rear bumper reinforcement			\$ 400.00	✓
1 pc	n/s rear bumper retainer			\$ 80.00	✓
1 pc	n/s rear bumper reflector			\$ 70.00	✓
1 pc	rear end panel			\$ 500.00	✓
1 pc	n/s tail gate → 1720			At \$ 1,900.00	✓
2 pcs	n/s tail gate hinges		\$ 250.00	lower At \$ 500.00	✓
1 pc	tail gate rubber			\$ 390.00	✓
1 pc	tail gate combo emblem			\$ 38.00	✓
1 pc	n/s tail lamp			\$ 350.00	✓
1 pc	n/s rear fender → 1630			At \$ 2,000.00	✓
1 pc	n/s rear fender under-shield			\$ 350.00	✓
				\$ 7,378.00	X
	Less 10%			\$ 737.80	
				\$ 6,640.20	
1 set	rear bumper sensor	S.Nett		\$ 200.00	✓
1 tube	rear windscreen sealant	S.Nett		\$ 40.00	✓
	To putty & spray paint			\$ 1,000.00	800
	To transfer tail gate fitting.			\$ 80.00	60
	To remove & refic rear n/s windscreen glass.			\$ 100.00	✓
	To remove & refix fuel tank.			\$ 80.00	60
	To remove & refix rear trimming.			\$ 60.00	✓
	To anti-rust.			\$ 120.00	60
	Labour charges			\$ 1,200.00	900
TG/VL	TOTAL			\$ 9,520.20	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: