

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

LKe

NTUC

Date: 19.08.2020
Time: 18:05:08
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305417519
REGN NO : SHC1832Z
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 28.04.2016
DATE/TIME IN : 19.08.2020 11:45
ACCIDENT DATE : 18.08.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	I40V3 BUMPER W LIP & FOG	1 L	1,052.20	20.00	841.76	de
0002 04-01-0103-0638-G	I40VC BRKT ASSY-FR BPR UP	1 L	22.40	20.00	17.92	Xun
0003 04-01-0103-0640-G	I40VC BRACKET-FR BUMPER S	1 L	24.60	20.00	19.68	Xun
0004 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	nei
0005 04-01-0103-0633-G	I40V2 COVER-FR BUMPER RH	1 L	93.60	20.00	74.88	cut
Headlamp RH \$1388 20% - \$1110.40						2044.64
SUB-TOTAL :						971.84

JOB NATURE

0000 20-05	FRT FENDER ADVERTISMENT LOGO RH	100.00	cut
0001 L	PANEL BEATING (repair frt fender Rh)	400.00	280
0002 23-502	SPRAYPAINT ON AFFECTED AREA	450.00	400
0003 20-00	TUFF COAT ON AFFECTED PARTS.	530.00	30 840.
Wiring - \$30			
Tang Mi 97445745			
20/8/20 C/pu			
Resury after repair			
02 days			
Tang Mi 97445745			
Houli			
SUB-TOTAL :		1,480.00	

\$2884.64

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before after repair, painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

25/8/2020 2 days #