

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

28-Apr-15

ESTIMATE REPAIR BILL FOR KIA MAGENTIS REGN NO: SHD 1307 T

1 pc	rear n/s tail lamp <i>cra</i>	\$	339.90	
1 pc	Rear bumper <i>deform</i>	\$	501.60	
2 pcs	Rear bumper side retainer @ \$14.30 <i>n/s cra, o/s svc</i>	\$	28.60	<i>4</i>
2 pcs	Rear bumper side holder @ \$30 <i>n/s cra, o/s svc</i>	\$	60.00	<i>4</i>
1 pc	Rear n/s fender innershield <i>svc</i>	\$	39.70	<i>x</i>
		\$	969.80	
		Less 10%	\$	96.98
			\$	872.82

S/NETT

1 pc	Rear n/s fender sticker <i>rec</i>	\$	60.00	
1 set	Rear bumper clips <i>rec</i>	\$	45.50	
				<i>3 day LS LKK Henry 97884050 28/4/15 1030hrs After repair photo.</i>
To check wiring		\$	40.00	<i>30</i>
To check wheel alignment		\$	80.00	<i>x</i>
To dismantle and refit the inner garnishes, inner lining, inner trims, etc to facilitate repairs.		\$	150.00	<i>60</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of rear n/s fender, etc		\$	600.00	<i>400</i>
To putty and spray painting on the rear bumper, rear n/s fender		\$	500.00	<i>360</i>
To apply rustproofing on the repaired and replaced panels		\$	200.00	<i>30</i>
Total		\$	2,548.32	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: