



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III19020295/Dtf3e2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 21-08-2020



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 2344U	Veh. Inspected	FBJ 6607J
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT19110333	Excess (\$)	0.00
Assign From	MEKAVATHANAN	Assign Date	12/07/2020

2. Vehicle Particulars & Condition

Make & Model	YAMAHA FJR1300	c.c	1298
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JYARP231000002877	Colour	BLACK
Odometer	88292	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/70Z R17	BRIDGESTONE	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	180/55Z R17	MICHELIN	5 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	13/11/2019	Inspection Date	15/11/2019
Survey held at	ONG MOTOR TRADING NO. 464 MACPHERSON ROAD SINGAPORE 368182		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------