

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: [Nora.khai@premiumauto.com.sg](mailto:Nora.khai@premiumauto.com.sg) / [claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg)

**WIP : 46247**

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0589/2020/NS/TT  
**Date** : 21-Aug-20

**Vehicle NOT IN workshop. Kindly arrange for survey.**

**Your insured veh no : SCH 5902 L**

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

*Hi Adrian*

*3 days - ok - jb - 1 Feb 21*

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Sim Yeow Ling  
**Address** : 09 Jalan Pelatok  
488448  
**Telephone** : (HP) +65 96420121  
**Type of Claim** : Third Party Claims  
**Policy No.** : PNPV2019-00016673  
**Vehicle No** : **SMF 5737 P**  
**Model Code** : Audi A3 Sportback 1.0 TF  
**Model / Year** : 16/11/2018  
**Engine No** : CHZ A93161  
**Chassis No** : WAUZZZ8V1KA003064  
**Mileage** : -  
**Date In** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 20-Aug-20  
**Place of Accident** : SLIP ROAD LOYANG AVE

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle. SMF 5737 P

| S/n                         | Nature of Jobs                                                                                                         | Estimated Charges |    |                 |                    |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------|-------------------|----|-----------------|--------------------|
| 1                           | To remove and transfer rear parking aid. Check function.                                                               | S/N               | \$ | 280.00          |                    |
| 2                           | To renew rear winscreen to facilitate rear lid renewal.                                                                | S/N               | \$ | 480.00          |                    |
| 3                           | To install solar film for rear windscreen.                                                                             | S/N               | \$ | 400.00          |                    |
| 4                           | To carry out water seepage test for rear windscreen.                                                                   | S/N               | \$ | 200.00          |                    |
| 5                           | To remove and transfer rear lid's convenience lock system, wire harness for tail lights and rear wiper assy.           | S/N               | \$ | 480.00          |                    |
| 6                           | To dismantle and renew rear bumper and rear lid. Re-organise crash management components. Reinstall all parts removed. |                   | \$ | 2,100.00        | \$ 500.00          |
| 7                           | To respray rear bumper and rear lid.                                                                                   |                   | \$ | 2,000.00        | \$ 1,100.00        |
| 8                           | To carry out diagnostic check.                                                                                         | S/N               | \$ | 192.00          | \$ 192.00          |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                        | :                 | \$ | <b>6,132.00</b> | <b>\$ 1,792.00</b> |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SMF 5737 P

| S/N                  | Parts Description                       | Damaged Parts & Prices |             |
|----------------------|-----------------------------------------|------------------------|-------------|
|                      |                                         | S/Nett                 | Remarks     |
| 1                    | REAR BUMPER                             | \$ 1,847.00            | \$ 1,477.60 |
| 2                    | REAR BUMPER FIXING PARTS                | \$ 191.00              |             |
| 3                    | REAR BUMPER LOCKING MECHANISM - LH / RH | 2 \$ 28.00             |             |
| 4                    | REAR BUMPER SPOILER                     | \$ 234.00              | \$ 187.20   |
| 5                    | REAR LIGHT REFLECTOR - LH / RH          | 2 \$ 60.00             |             |
| 6                    | REAR BUMPER SIDE REINFORCEMENT BEAM     | \$ 565.00              |             |
| 7                    | REAR BUMPER BRACKET - LH                | \$ 27.00               |             |
| 8                    | REAR BUMPER BRACKET - RH                | \$ 28.00               |             |
| 9                    | REAR PARKING AID SENSOR - INNER / OUTER | 2 TBC                  |             |
| 10                   | REAR PARKING AID SEAL RING              | 4 \$ 14.00             |             |
| 11                   | REAR LID                                | \$ 1,981.00            |             |
| 12                   | REAR LID ATTACHMENT PARTS               | \$ 291.00              |             |
| 13                   | REAR LID FLAP GASKET                    | \$ 203.00              |             |
| 14                   | REAR LID LOCK                           | \$ 169.00              |             |
| 15                   | PACKING ADHESIVE                        | \$ 18.00               | \$ 14.40    |
| 16                   | AUDI EMBLEM                             | \$ 122.00              | \$ 97.60    |
| 17                   | A3 INSCRIPTION                          | \$ 95.00               | \$ 75.36    |
| 18                   | REAR WINDSCREEN                         | \$ 805.00              |             |
| 19                   | PRIMER                                  | \$ 19.00               |             |
| 20                   | SPOILER FIXING PARTS                    | \$ 164.00              |             |
| 21                   | REAR NO PLATE                           | S/N \$ 60.00           |             |
| 22                   | REAR WINDSCREEN SEALANT                 | S/N \$ 200.00          |             |
| 23                   | SUNDRIES                                | \$ 300.00              |             |
| TOTAL SPARE PARTS    |                                         | : \$ 7,421.00          | \$ 1,852.16 |
| TOTAL LABOUR CHARGES |                                         | : \$ 6,132.00          | \$ 1,792.00 |
| GRAND TOTAL          |                                         | : \$ 13,553.00         | \$ 3,644.16 |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

bl-22/10/20

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** :  
**Surveyed Date** :  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** :

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant