

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 46247

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0589/2020/NS
Date	:	21-Aug-20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured veh no : SCH 5902 L

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Sim Yeow Ling
Address	:	09 Jalan Pelatok 488448
Telephone	:	(HP) +65 96420121
Type of Claim	:	Third Party Claims
Policy No.	:	PNPV2019-00016673
Vehicle No	:	SMF 5737 P
Model Code	:	Audi A3 Sportback 1.0 TF
Model / Year	:	16/11/2018
Engine No	:	CHZ A93161
Chassis No	:	WAUZZZ8V1KA003064
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	20-Aug-20
Place of Accident	:	SLIP ROAD LOYANG AVE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMF 5737 P

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00 ✓
2	To renew rear winscreen to facilitate rear lid renewal.	S/N \$ 480.00 ✗
3	To install solar film for rear windscreen.	S/N \$ 400.00 ✗
4	To carry out water seepage test for rear windscreen.	S/N \$ 200.00 ✗
5	To remove and transfer rear lid's convenience lock system, wire harness for tail lights and rear wiper assy.	S/N \$ 480.00 ✗
6	To dismantle and renew rear bumper and rear lid. Re-organise crash management components. Reinstall all parts removed.	\$ 2,100.00 500
7	To respray rear bumper and rear lid.	\$ 2,000.00 1100
8	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>6,132.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6041 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 5737 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER <i>Disbled</i>	\$ 1,847.00	✓
2	REAR BUMPER FIXING PARTS <i>new</i>	\$ 191.00	✗
3	REAR BUMPER LOCKING MECHANISM - LH / RH <i>new</i>	2 \$ 28.00	✗
4	REAR BUMPER SPOILER <i>new</i>	\$ 234.00	✗
5	REAR LIGHT REFLECTOR - LH / RH <i>new</i>	2 \$ 60.00	✗
6	REAR BUMPER SIDE REINFORCEMENT BEAM <i>?</i>	\$ 565.00	?
7	REAR BUMPER BRACKET - LH <i>new</i>	\$ 27.00	✗
8	REAR BUMPER BRACKET - RH <i>new</i>	\$ 28.00	✗
9	REAR PARKING AID SENSOR - INNER / OUTER <i>?</i>	2 TBC	?
10	REAR PARKING AID SEAL RING <i>?</i>	4 \$ 14.00	?
11	REAR LID <i>Repair</i>	\$ 1,981.00	✗
12	REAR LID ATTACHMENT PARTS <i>new</i>	\$ 291.00	✗
13	REAR LID FLAP GASKET <i>new</i>	\$ 203.00	✗
14	REAR LID LOCK <i>new</i>	\$ 169.00	✗
15	PACKING ADHESIVE <i>new</i>	\$ 18.00	✓
16	AUDI EMBLEM <i>new</i>	\$ 122.00	✓
17	A3 INSCRIPTION <i>new</i>	\$ 95.00	✓
18	REAR WINDSCREEN <i>new</i>	\$ 805.00	✗
19	PRIMER <i>new</i>	\$ 19.00	✗
20	SPOILER FIXING PARTS <i>new</i>	\$ 164.00	✗
21	REAR NO PLATE	S/N \$ 60.00	✗
22	REAR WINDSCREEN SEALANT <i>new</i>	S/N \$ 200.00	✗
23	SUNDRIES <i>?</i>	\$ 300.00	?
TOTAL SPARE PARTS		: \$ 7,421.00	
TOTAL LABOUR CHARGES		: \$ 6,132.00	
GRAND TOTAL		: \$ 13,553.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adam L*
Surveyed Date : *21/08/20*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 0 Days*

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant