

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 46258

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0590/2020/NS
Date : 21-Aug-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Qiu Wei
Address : 21 Bedok Reservoir View
#09-02
Singapore 478936
Telephone : HP +65 92974998
Type of Claim : Own Damage Claim
Policy No. : 1900142676
Vehicle No : **SMN 7120 M**
Model Code : Audi A3 sportsback 1.0 TFSI
Model / Year : Aug-19
Engine No : CHZ C31794
Chassis No : WAUZZZ8V1KA107862
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-May-20
Place of Accident : People's Park Complex

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMN 7120 M

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer lhs front door;s multi-lock system and power window devices. Inspect for damages.	S/N \$ 280.00 ✓	
2	To dismantle and renew lhs front door. To repair lhs sill panel. Re-organise crash management components. Reinstall all parts removed.	\$ 1,400.00 ✓ 1200	1000 2 x 550 = 1100
3	To respray lhs front door, lhs sill panel, door handle and rhs rear fender.	\$ 3,000.00 ✓	Handle : 100 1200
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 4,872.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 7120 M

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT DOOR - LH <i>Dented</i>	\$ 2,267.00	✓
2	FRONT DOOR OUTER SEAL - LH <i>per</i>	NEC \$ 159.00	✓
3	BONDING AGENT <i>?</i>	NEC \$ 47.00	?
4	CLEANING SOLUTION <i>?</i>	NEC \$ 65.00	?
5	FRONT DOOR CATCH <i>Access</i>	\$ 104.00	X
6	EXTERIOR DOOR HANDLE - LH <i>cut</i>	\$ 359.00	✓
7	DOOR HANDLE CAP <i>Not in</i>	\$ 51.00	X
8	STONE CHIP <i>on</i>	S/N \$ 180.00	✓
9	SUNDRIES <i>?</i>	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		: \$ 3,532.00	
TOTAL LABOUR CHARGES		: \$ 4,872.00	
GRAND TOTAL		: \$ 8,404.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel 6366 2323 Fax 6841 1183

Telefax

Name

:

Adnan

Surveyed Date

:

21/08/20

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

Not Authorised, 04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly

For inspection of vehicle, please refer to Ms Norah Khai at

Tel 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant