

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SJG2213J
Accident Date : 13-Jul-2020

Our Ref : 020073 (AIG) / CHAN

TANG YAN HIM
993 BUKIT TIMAH ROAD
#05-14
Singapore 589631

No. : 06193

Date : 15-Jul-2020

PAGE : 1

*Not Authorized
Resurvey Before
3 days*

ESTIMATED COST OF REPAIR FOR M/BENZ C180 AVANTAGRDE SGX9293C

1 pc	Rear bumper fascia	R	1,831.00	✓
1 pc	Rear bumper reinforcement	R	751.00	X
1 pc	Rear reinforcement inner parts	CM	155.00	✓
1 pc	Rear bumper lower garnish	R	295.00	✓
2 pcs	Lower garnish parking sensor		1,288.00	✓
1 pc	rear lower garnish chrome	CM	326.00	✓
			4,646.00	
			Less 10% :	464.60

4,181.40

To putty and spray replaced parts

500.00 *300*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

450.00 *250*

Total : S\$ 5,131.40

Singapore Dollars Five Thousand One Hundred and
Thirty One and Cents Forty Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: