

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06193

Vehicle Insured : SJG2213J  
Accident Date : 13-Jul-2020

Date : 15-Jul-2020

Our Ref : 020073 (AIG) / CHAN

PAGE : 1

TANG YAN HIM  
993 BUKIT TIMAH ROAD  
#05-14  
Singapore 589631

*Not Authorised  
Resurvey Before  
3 days*

## ESTIMATED COST OF REPAIR FOR M/BENZ C180 AVANTAGRDE SGX9293C

1 pc	Rear bumper fascia	B	1,831.00	✓
1 pc	Rear bumper reinforcement		751.00	?
1 pc	Rear reinforcement inner parts		155.00	?
1 pc	Rear bumper lower garnish	RM	295.00	✓
4 pcs	Lower garnish parking sensor	@ S\$322.00	1,288.00	?
1 pc	rear lower garnish chrome	CM	326.00	✓
			4,646.00	
Less 10% :			464.60	

4,181.40

To putty and spray replaced parts

500.00 *30d*

To remove, cut-out damaged parts,  
panel beating, welding, align,  
refix and to renew above parts

450.00 *25d*

Total : S\$ 5,131.40

Singapore Dollars Five Thousand One Hundred and  
Thirty One and Cents Forty Only

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: