



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

RIAZ LLC

Ref : CS/LAW20006903/Gqf3s2-1

133 NEW BRIDGE ROAD  
#09-09 CHINATOWN POINT SINGAPORE 059413

Date : 01-09-2020



Code : L135

### 1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

<b>Insured Veh.</b>	SKE 9073Z	<b>Veh. Inspected</b>	SDM 12A
<b>Policy No.</b>	D17MTPV01005692	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	WAN.512360.J	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	ANTHONY CHEY	<b>Assign Date</b>	21/08/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	VOLKSWAGEN GOLF 1.2	<b>c.c</b>	1197
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	WVWZZZAUZGW277658	<b>Colour</b>	BLUE
<b>Odometer</b>	63874	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	205/55 R16	PIRELLI	5 mm
<b>L/H Front Tyre</b>	205/55 R16	PIRELLI	5 mm
<b>R/H Rear Tyre</b>	205/55 R16	PIRELLI	5 mm
<b>L/H Rear Tyre</b>	205/55 R16	PIRELLI	5 mm

### 4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.  
REPAIR CONDITION SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	20/02/2018	<b>Inspection Date</b>	24/08/2020
<b>Survey held at</b>	833 MOTORSPORTS BLK 20 SIN MING IND.EST.SECTOR A #01-16 SINGAPORE 575678		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**