



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /SELENA AKHBAR Reg No/Reg Date SMT1609D / 30/03/202 Date In/Mileage / 0 Chassis No KNAF3416ML5069616 Engine No G4FGKH755883 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	21/08/2020/ 14:26	Bod	442 / CocoLu	19789			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2400.00
RENEW FRT BUMPER, BONNET, FRT SUPPORT PANEL, FRT FEDNER LH								2000
FRT DOOR LH, WINDMIRROR LH, REPAIR FRT CHASSIS LH, REAR DOOR LH,								
SIDE SKIRT LH,								
E PNT98000								3500.00
SPRAY PAINT FOR FRT BUMPER, FRT AIRDAM, BONNET, FRT FENDER LH								2800
FRT DOOR LH, REAR DOOR LH, SIDE SKIRT LH, WINDMIRROR LH, FRT CHASSIS L								100.00
E PNT88000								80.00
REMOVE & INSTALL AIRCON CONDENSOR								
M SUNDRY								50.00
TOP UP AIRCON GAS ?								
M SUNDRY								120.00
FRT NUMBER PLATE WITH FRAME								
M SUNDRY								30.00
APPLY SEALANT FOR ACCIDENT PORTION								120.00
A 90000001								
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
B WHEELALIGNMENT								30.00
To Conduct Computerize Full Wheel Alignment								
M SUNDRY								
TRANSFER NEW RIM ?								200 300.00
A 90000001								400.00
RENEW FRT UNDER CARRAIGE								
A 90000001								200 400.00
RENEW DASHBOARD								
A 90000001								120 300.00
RENEW SEAT BELT AND AIRBAG SYSTEM								
E PNT88000								1600.00
REMOVE & INSTALL FRT DOOR TRIMS AND GLASS								
E PNT88000								

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /SELENA AKHBAR Reg No/Reg Date SMT1609D / 30/03/202 Date In/Mileage / 0 Chassis No KNAF3416ML5069616 Engine No G4FGKH755883 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	21/08/2020/ 14:26	Bod	442 / CocoLu	19789			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
RENEW REAR AIRDAM, REAR BUMPER, BOOTLID, REAR END PANEL, 3 days								1,200
REPAIR REAR FENDER LH,								100.00
E PNT88000								
REMOVE & INSTALL PARKING SENSOR								120.00
E PNT88000								
REMOVE & INSTALL REAR COMPARTMENT TRIMS								2100.00
E PNT88000								
REMOVE & INSTALL FRT & REAR AIRDAM								1750
E PNT98000								
SPRAY PAINT FOR REAR AIRDAM, REAR BUMPER, BOOTLID, REAR FENDER LH 5 part								220.00
REAR END PANEL,								
M SUNDRY								
SUPPLY PARKING SENSOR ?								380.00
M SUNDRY								
SUPPLY FRT LEFT RIM ?								80.00
M SUNDRY								
APPLY SEALANT FOR ACCIDENT PORTION ON REAR X								40.00
M SUNDRY								
C&C LOGO / Nec								20.00
M SUNDRY								
Sundry / Nec								
M NEW K3 2020 RUNWAY RED CR5 / CR1					1.00	1721.00	00.00	1721.00
M COVER-FR BUMPER / PD.					1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER / CR1					1.00	262.00	20.00	209.60
M COVER-FR BUMPER FOG LAMP, LH / MIS					1.00	15.00	20.00	12.00
M LAMP ASSY-FRONT FOG, LH / MIS					1.00	303.00	20.00	242.40
M GRILLE ASSY-RADIATOR / CR1					1.00	328.00	20.00	262.40
M MOULDING-FRONT BUMPER, LH / MIS					1.00	36.00	20.00	28.80
M LAMP ASSY-SIDE REPEATER, LH / MIS					1.00	143.00	20.00	114.40
M AIR DUCT-FR BUMPER, LH / MIS					1.00	14.00	20.00	11.20
M BRACKET-FR BUMPER UPR SIDE MTG / BK					1.00	22.00	20.00	17.60
M ABSORBER-FRONT BUMPER ENERGY / Nec.					1.00	84.00	20.00	67.20
M STIFFNER-FR BPR LWR ? nec ✓					1.00	114.00	20.00	91.20

Confirm &amp; accepted by

1 day 400

part - 360

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



### ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /SELENA AKHBAR Reg No/Reg Date SMT1609D / 30/03/202 Date In/Mileage / 0 Chassis No KNAF3416ML5069616 Engine No G4FGKH755883 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	21/08/2020/ 14:26	Bod	442 / CocoLu	19789			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	PANEL ASSY-HOOD	pp			1.00	1502.00	20.00	1201.60
M	HINGE ASSY-HOOD, LH	BT			1.00	43.00	20.00	34.40
M	PANEL-FENDER, LH	cmu			1.00	430.00	20.00	344.00
M	INSULATOR-FENDER LH	? nec			1.00	27.00	20.00	21.60
M	PAD-HOOD INSULATING	cmu			1.00	156.00	20.00	124.80
M	LATCH ASSY-HOOD	? nn			1.00	103.00	20.00	82.40
M	GUARD ASSY-FRONT WHEEL, LH	cmu			1.00	95.00	20.00	76.00
M	BEAM COMPLETE-FR BUMPER	pp			1.00	497.00	20.00	397.60
M	CARRIER ASSY-FRONT END MODULE	cmu			1.00	675.00	20.00	540.00
M	BRACKET ASSY-FENDER & BUMPER, L	? nn			1.00	9.00	20.00	7.20
M	BRACKET ASSY-FENDER & BPR MTG, L	? nn			1.00	14.00	20.00	11.20
M	LAMP ASSY-HEAD, LH	cmu			1.00	1219.00	20.00	975.20
M	MIRROR ASSY-OUTSIDE RR VIEW, LH	? nn			1.00	559.00	20.00	447.20
M	PANEL ASSY-FRONT DOOR, LH	pp			1.00	1277.00	20.00	1021.60
M	COVER-RR BUMPER	cmu			1.00	651.00	20.00	520.80
M	COVER-RR BUMPER LWR	? cra			1.00	241.00	20.00	192.80
M	COVER-RR BUMPER FOG LAMP, LH	? cru			1.00	19.00	20.00	15.20
M	LAMP ASSY-SIDE T/SIGNAL, LH	? nn			1.00	181.00	20.00	144.80
M	BRACKET-RR BEAM UPR MTG, LH	? nn			1.00	9.00	20.00	7.20
M	BEAM-RR BUMPER	? cra			1.00	318.00	20.00	254.40
M	BRACKET-RR BEAM LWR, CTR	? nn			1.00	6.00	20.00	4.80
M	ANTENNA ASSY-SMARTKEY	? nn			1.00	46.00	20.00	36.80
M	STAY-RR BUMPER LH	? broken			1.00	65.00	20.00	52.00
M	BRACKET ASSY-RR BPR SIDE UPR, L	? broken			1.00	25.00	20.00	20.00
M	BRACKET ASSY-RR BPR SIDE UPR, R	? nn			1.00	31.00	20.00	24.80
M	PANEL ASSY-TRUNK LID	pp			1.00	1297.00	20.00	1037.60
M	PANEL ASSY-BACK	pp			1.00	324.00	20.00	259.20
M	TRIM ASSY-RR TRANSVERSE	? nn			1.00	41.00	20.00	32.80
M	ORNAMENT-KIA NO.115	Front / nrc			1.00	32.00	20.00	25.60
M	LOGO ASSY-KIA SUB	nrc			1.00	32.00	20.00	25.60
M	EMBLEM-CERATO	nrc			1.00	28.00	20.00	22.40
M	ARM COMPLETE-FR LWR, LH	? Bent			1.00	286.00	20.00	228.80
M	HUB ASSY-FR WHEEL	? Jammed			1.00	436.00	20.00	348.80

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



### ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /SELENA AKHBAR Reg No/Reg Date SMT1609D / 30/03/202 Date In/Mileage / 0 Chassis No KNAF3416ML5069616 Engine No G4FGKH755883 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	21/08/2020/ 14:26	Bod	442 / CocoLu	19789
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M KNUCKLE-FRONT AXLE, LH ? nn		1.00	350.00	20.00	280.00
M GUARD-AIR, LH ? cracked		1.00	28.00	20.00	22.40
M CONDENSER ASSY-COOLER ? bent		1.00	687.00	20.00	549.60
M BRACKET ASSY-RADIATOR MTG, UPR ? nn		1.00	29.00	20.00	23.20
M RADIATOR ASSY ? bent		1.00	646.00	20.00	516.80
M CRASH PAD ASSY-MAIN Dash board / BK } - photo.		1.00	1279.00	20.00	1023.20
M MODULE ASSY-AIR BAG CONTROL / Nec } - photo.		1.00	1025.00	20.00	820.00
P SENSOR ASSY-A TYPE CRASH / Nec } - photo.		2.00	54.00	20.00	86.40
M MODULE ASSY-STRG WHEEL AIR BAG / Nec } - photo.		1.00	922.00	20.00	737.60
M AIR BAG ASSY-PASSENGER / Nec		1.00	1275.00	20.00	1020.00
M STRUT ASSY-FR, LH ? bent		1.00	280.00	20.00	224.00
M ADJUSTER ASSY-HEIGHT ? nn		2.00	37.00	20.00	59.20
M S/BELT ASSY-FR RH / Jam		1.00	317.00	20.00	253.60
M BUCKLE ASSY-FR S/BELT, RH ? nn		1.00	114.00	20.00	91.20
M S/BELT ASSY-FR LH / Jam		1.00	315.00	20.00	252.00
M BUCKLE ASSY-FR S/BELT, LH ? nn		1.00	179.00	20.00	143.20
M PANEL ASSY-UNDER COVER / CRU.		1.00	117.00	20.00	93.60
M LINK-STABILIZER ? bent		1.00	72.00	20.00	57.60
M DUCT ASSY-EXTENSION ? missing		1.00	144.00	20.00	115.20
M WIRING ASSY-FEM ? cut		1.00	91.00	20.00	72.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sunpin (Lkk)

Sunpin@lkkauto.com

8661 2627.

OP.

Rev.

Excess - TBC.

Confirm &amp; accepted by

Repair day - 16 days

35,603.80

7% GST on **Nett** 31,175.00 2182.25

Total Payable 33,357.25

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.