

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 24 Aug 2020

Preliminary Advice

Insured Vehicle No : SLC6703H

TP Vehicle No : F1093T

Make : YAMAHA X-1R

Date of Inspection : 21/08/2020

Inspection At : Teo Spray Painting (HQ)

BLK 6 DEFU LANE 10, DEFU IND PARK C #01-558
Singapore 539187

Accident Date : 14/08/2020

Assignment Date : 21/08/2020

Est. Duration of Repair : 3 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	914.00
Revised Amount	:S\$	844.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	844.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- () Lump Sum repair

(X) The above survey was conducted on a 'without prejudice' basis.