

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
HP: 8386 8989 EMAIL: atautoconsultant@gmail.com
Co. Reg. No. : 53368526E

NOT Authorized
11 Rm @ 7350k
Purvey After Paint
Folan

Date of Estimate: 20.08.2020
Vehicle No: SLT6619D
Owner: LOON XI YANG
Date of Accident: 20.08.2020
Make & Model: HYUNDAI TUCSON 1.6 GLS
Chassis No : KMHJ3812VJU606234

ESTIMATE FOR ACCIDENT VEHICLE NOS SLT6619D

PARTS

1	1 Tail gate → 1628
2	1 Tail gate lower number plate garnish
3	1 Tail gate reflector → 681.60
4	1 Tail gate emblem "HYUNDAI"
5	1 Tail gate emblem "TUCSON"
6	1 Tail gate emblem "TURBO"
7	1 Tail gate inner trim
8	1 Tail gate lock
9	1 Tail gate weather strip
10	1 Rear bumper 798
11	1 Rear bumper lower lid
12	1 Rear bumper reflector
13	1 Rear reinforcement
14	1 Rear end panel
15	1 Tail lamp LH
16	1 Tail lamp pocket panel
17	1 Rear fender LH →
18	1 Rear fender inner trim
19	1 Rear fender wheel arch garnish
20	1 Rear wheel inner garnish

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Ry	\$1,658.30	✓
CM	\$285.20	✓
Bu	\$871.90	✓
Re	\$59.70	✓
Re	\$59.70	✓
Re	\$59.70	✓
Re	\$256.20	X
Re	\$198.20	X
Re	\$234.10	X
Re	\$935.60	✓
Re	\$365.70	✓
CM	\$120.90	✓
CM	\$289.10	✓
Re	\$665.10	X
Bu	\$895.30	✓
Re	\$333.90	✓
Bu	\$2,042.70	✓
Re	\$836.40	X
Re	\$190.00	X
Re	\$185.30	X
SUB TOTAL		
\$10,543.00		
LESS 20 %		
\$2,108.60		
DISCOUNTED SUB TOTAL		
\$8,434.40		

S. NETT ITEM

1	1set Tail gate wind screen sealant
2	1set Rear fender quarter glass moulding
3	1set Bumper clips
4	1set Number plate & garnish
5	2 Reverse sensor original X 2
6	1 Bumper top anti scratches auto healing sticker
7	1 Ceramic coating for affected area

@ \$135.00

Re	\$180.00	✓
Re	\$158.00	✓
Re	\$50.00	✓
Re	\$60.00	X
Re	\$270.00	✓
Re	\$250.00	✓
Re	\$500.00	X
SUB TOTAL		
\$1,468.00		
LESS 0 %		
\$0.00		
DISCOUNTED SUB TOTAL		
\$1,468.00		

LABOUR

1	Panel beating for replace and repair affected parts
2	Spray painting on accident areas
3	Wiring charges
4	R/R tail gate wind screen
5	R/R rear fender quarter glass LH
6	R/R petrol pipe to facilitate hot work
7	R/R rear boot compartment/rear seat to facilitate repair
8	Apply undercoating to above affected areas

\$1200	1200.00	601
	1,500.00	1000
	100.00	201
	180.00	1201
na	180.00	601
	200.00	X
	300.00	601
	150.00	601
SUB TOTAL (LABOUR)		
\$2,730.00		