

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Aug 2020 Edit Reg		21 Aug 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: SEOW MUI MUI (XIAO MEIMEI) , ID: S7622702]									
Main Claimant: -									
Vehicle Reg. No.: FBJ2330H		Date of Loss: 17/08/2020 00:00 - :59 [78 Months and 7 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 4929508673SG		Policy/Cover Note No.: 1800156512 (Comprehensive)							
Vehicle Reg. No. (Insured): SMM1800D		Policy No. (Claimant):							
		Excess:							
Repairer: Primero Racing (enterprise Centre) (HQ) 20 Bukit Batok Crescent, #01-19 Enterprise Centre, 658080 Bukit Batok - Tel: 6262 3305									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 02/09/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBJ2330H (4929508673SG)
[SMM1800D]
TP**

**-
Aug 17 2020 12:00AM
[SEOW MUI MUI (XIAO MEIMEI)]
Primero Racing (enterprise Centre)**

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/08/20 17:54	Chassis Number	 Load JPG	☒
2	24/08/20 17:54	General View	 Load JPG	☒
3	24/08/20 17:54	General View	 Load JPG	☒
4	24/08/20 17:54	General View	 Load JPG	☒
5	24/08/20 17:54	General View	 Load JPG	☒
6	24/08/20 17:54	General View	 Load JPG	☒
7	24/08/20 17:54	General View	 Load JPG	☒
8	24/08/20 17:54	General View	 Load JPG	☒
9	24/08/20 17:54	General View	 Load JPG	☒
10	24/08/20 17:54	General View	 Load JPG	☒
11	24/08/20 17:54	General View	 Load JPG	☒
12	24/08/20 17:54	General View	 Load JPG	☒
13	24/08/20 17:54	General View	 Load JPG	☒
14	24/08/20 17:54	General View	 Load JPG	☒
15	24/08/20 17:54	General View	 Load JPG	☒
16	24/08/20 17:54	General View	 Load JPG	☒
17	24/08/20 17:54	General View	 Load JPG	☒
18	24/08/20 17:54	General View	 Load JPG	☒
19	24/08/20 17:54	General View	 Load JPG	☒
20	24/08/20 17:54	General View	 Load JPG	☒
21	24/08/20 17:54	General View	 Load JPG	☒
22	24/08/20 17:54	General View	 Load JPG	☒
23	24/08/20 17:54	General View	 Load JPG	☒
24	24/08/20 17:54	General View	 Load JPG	☒
25	24/08/20 17:54	General View	 Load JPG	☒
26	24/08/20 17:54	General View	 Load JPG	☒
27	24/08/20 17:54	General View	 Load JPG	☒
28	24/08/20 17:54	General View	 Load JPG	☒
29	24/08/20 17:54	General View	 Load JPG	☒
30	24/08/20 17:54	General View	 Load JPG	☒
31	24/08/20 17:54	General View	 Load JPG	☒
32	24/08/20 17:54	General View	 Load JPG	☒
33	24/08/20 17:54	General View	 Load JPG	☒
34	24/08/20 17:54	General View	 Load JPG	☒
35	24/08/20 17:54	General View	 Load JPG	☒
36	24/08/20 17:54	General View	 Load JPG	☒
37	24/08/20 17:54	General View	 Load JPG	☒
38	24/08/20 17:54	General View	 Load JPG	☒
39	24/08/20 17:54	General View	 Load JPG	☒
40	24/08/20 17:54	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	24/08/20 17:54	General View	 Load JPG	☒
42	24/08/20 17:54	General View	 Load JPG	☒
43	24/08/20 17:54	General View	 Load JPG	☒
44	24/08/20 17:54	General View	 Load JPG	☒
45	24/08/20 17:54	General View	 Load JPG	☒
46	24/08/20 17:54	General View	 Load JPG	☒
47	24/08/20 17:54	General View	 Load JPG	☒
48	24/08/20 17:54	General View	 Load JPG	☒
49	24/08/20 17:54	General View	 Load JPG	☒
50	24/08/20 17:54	General View	 Load JPG	☒
51	24/08/20 17:54	General View	 Load JPG	☒
52	24/08/20 17:54	General View	 Load JPG	☒
53	24/08/20 17:54	General View	 Load JPG	☒
54	24/08/20 17:54	General View	 Load JPG	☒
55	24/08/20 17:54	General View	 Load JPG	☒
56	24/08/20 17:54	General View	 Load JPG	☒
57	24/08/20 17:54	General View	 Load JPG	☒
58	24/08/20 17:54	General View	 Load JPG	☒
59	24/08/20 17:54	General View	 Load JPG	☒
60	24/08/20 17:54	General View	 Load JPG	☒
61	24/08/20 17:54	General View	 Load JPG	☒
62	24/08/20 17:54	General View	 Load JPG	☒
63	24/08/20 17:54	General View	 Load JPG	☒
64	24/08/20 17:54	General View	 Load JPG	☒
65	24/08/20 17:54	General View	 Load JPG	☒
66	24/08/20 17:54	General View	 Load JPG	☒
67	24/08/20 17:54	General View	 Load JPG	☒
68	24/08/20 17:54	General View	 Load JPG	☒
69	24/08/20 17:54	General View	 Load JPG	☒
70	24/08/20 17:54	General View	 Load JPG	☒
71	24/08/20 17:54	General View	 Load JPG	☒
72	24/08/20 17:54	General View	 Load JPG	☒
73	24/08/20 17:54	General View	 Load JPG	☒
74	24/08/20 17:54	General View	 Load JPG	☒
75	24/08/20 17:54	General View	 Load JPG	☒
76	24/08/20 17:54	General View	 Load JPG	☒
77	24/08/20 17:54	General View	 Load JPG	☒
78	24/08/20 17:54	General View	 Load JPG	☒
79	24/08/20 17:54	General View	 Load JPG	☒
80	24/08/20 17:54	General View	 Load JPG	☒
81	24/08/20 17:54	General View	 Load JPG	☒
82	24/08/20 17:54	General View	 Load JPG	☒
83	24/08/20 17:54	General View	 Load JPG	☒
84	24/08/20 17:54	General View	 Load JPG	☒
85	24/08/20 17:54	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	25/08/20 17:01	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG20008852/R1TF3S2**Date:** 21/09/2020**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800156512
Claimant Vehicle No :	FBJ2330H	Insured Vehicle No :	SMM1800D
Date of Loss:	17/08/2020	Nature of Claim:	TP
		Claim No:	4929508673SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBJ2330H	Engine No:	SC59E2501120
Make & Model:	HONDA CBR1000RR, 999cc (M)	Chassis No:	JH2SC59A9EK600429
Reg. Date:	10/02/2014 (Man. Year: 2014)	Odometer:	0 km
Colour:	Multi-colour		
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	120/70 ZR17	Rear Tyre Size:	190/55 ZR17
Front Left Side:	MITAS 4 mm	Rear Left Side:	MITAS 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	21/08/2020	
Date Inspected:	24/08/2020 Inspected At:	Primero Racing (enterprise Centre) (HQ) 20 Bukit Batok Crescent, #01-19 Enterprise Centre Singapore 658080
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP LH	Cracked	0.00 F	*- F
2	1		*FRONT WING MIRROR	Scratched	0.00 F	*- F
3	1		*HANDLE BAR BALANCER LH	Scratched	0.00 F	*- F
4	1		*HANDLE BAR BALANCER RH COVER	Distorted	0.00 F	*- F
5	1		*CLUTCH LEVER	Scratched	0.00 F	*- F
6	1		*SIDE FAIRING LH	Cracked	0.00 F	*- F
7	1		*FAIRING LOWER	Scratched	0.00 F	*- F
8	1		*FRONT COWLING	Cracked	0.00 F	*- F
9	1		*OIL FILTER COVER	Scratched	0.00 F	*- F
10	1		*EXHAUST GARNISH	Scratched	0.00 F	*- F
11	1		*FRONT TYRE RIM	Repair	0.00 F	*- F
12	1		*REAR FOOT REST	Scratched	0.00 F	*- F
13	1		*EXHAUST MUFFLER ASSY	Scratched	0.00 F	*- F
F=Franchise part.						
					Total Parts (\$\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >