

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 46147

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0586/2020/NS
Date : 20-Aug-20

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ns Tan Seok Chin
Address : 957 Bukit Timah Road
#04-16
Singapore 589653
Telephone : HP +65 96384462
Type of Claim : Own Damage Claims
Policy No. : 1900190251
Vehicle No : **SMP 7942 Y**
Model Code : Audi A6 Design 2.0 TFSI S
Model / Year : 16/10/2019
Engine No : DLH 054572
Chassis No : WAUZZZF23KN123109
Mileage : 9431
Date In : 20-Aug-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 19-Aug-20
Place of Accident : NUH

Car-in

27/8/2020

LA/TOH

wip=46147

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

3 days

Material List for Accident Vehicle Regn No. SMP 7942 Y

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER CLOSING ELEMENT - LOWER	\$ 208.00	cut ✓
2	ENGINE UNDERSHIELD	\$ 628.00	X
3	FRONT WISHBONE LINK - RH	\$ 533.00	✓ BT/CMT ← Subject to approve
4	FRONT SUSPENSION GUIDE - RH	\$ 932.00	?
5	FRONT GUIDE - RH UPPER	\$ 333.00	?
6	REAR GUIDE - RH UPPER	\$ 333.00	?
7	WHEEL BEARING HOUSING - RH	\$ 894.00	?
8	SWIVEL JOINT	\$ 191.00	?
9	WHEEL HUB	\$ 465.00	?
10	DOUBLE ANGLED BALL BEARING	\$ 239.00	?
11	SUSPENSION FORKS - RH	\$ 356.00	?
12	COUPLING ROD	\$ 127.00	?
13	FRONT ANTI-ROLL BAR	\$ 490.00	?
14	SHOCK ABSORBER BEARING - RH	\$ 131.00	?
15	TIE ROD END - RH	\$ 195.00	?
16	TRACK ROD	\$ 124.00	?
17	WISHBONE - LOWER	\$ 868.00	?
18	WISHBONE - UPPER FRONT	\$ 384.00	?
19	FRONT WISHBONE - RH	\$ 587.00	?
20	REAR WISHBONE - RH	\$ 292.00	?
21	REAR TRACK ROD - RH	\$ 197.00	?
22	WHEEL BEARING HOUSING - RH	\$ 971.00	?
23	WHEELHUB	\$ 667.00	?
24	STONE CHIP GUARD - RH	\$ 44.00	X
25	ALUMINIUM RIM - RH	2 \$ 2,534.00	dd ✓
26	RADIAL TYRE	2 \$ 2,454.00	punctured ✓ 90%
27	SUNDRIES	\$ 300.00	?
TOTAL SPARE PARTS		: \$ 15,477.00	
TOTAL LABOUR CHARGES		: \$ 7,032.00	
GRAND TOTAL		: \$ 22,509.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

supp

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle, SMP 7942 Y

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	?
2	To remove and renew rhs front wheel suspension assy. To inspect for further damages.	S/N \$	1,800.00	? plus.
3	To remove and renew rhs rear wheel suspension assy. To inspect further for damages.	S/N \$	1,800.00	? plus.
4	To dismantle and reinstall front bumper. To renew front bumper lower closing element and noise insulation. Re-organise crash management components. Reinstall all parts removed.	\$	1,200.00	500.
5	To respray front bumper.	\$	1,000.00	X
6	To renew rhs front rim with tyre and rhs rear rim with tyre. To carry out pre and post wheel alignment test.	S/N \$	560.00	✓
7	To carry out diagnostic check.	S/N \$	192.00	✓
SUB TOTAL LABOUR CHARGES		:	<u>\$ 7,032.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Tanpin 97495719/67418434
21/8/20 @ 1215 pm
Repair, not Authorised
Ex: to be advise
o3 days
Repairing new parts
Tanpin @ Khentowan

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant